

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SUBJECT		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL ANOTHER WELL OR PLUG A WELL TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)		5a. Indicate Type of Lease State ☐ Fee ☒ 5. State Oil & Gas Lease No.																
1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER- 2. Name of Operator Cities Service Oil Company 3. Address of Operator P. O. Box 1919, Midland, Texas 79702 4. Location of Well UNIT LETTER <u>H</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>810</u> FEET FROM THE <u>East</u> LINE, SECTION <u>29</u> TOWNSHIP <u>21S</u> RANGE <u>27E</u> N.M.P.M.		7. Unit Agreement Range 8. Name of Lease Name Simpson "A" 9. Well No. 1 10. Field and Pool, or Wildcat La Huerta (Wolfcamp)																
15. Elevation (Show whether DF, RT, GR, etc.) 3154' GR		12. County Eddy																
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data <table border="0"> <tr> <td colspan="2">NOTICE OF INTENTION TO:</td> <td colspan="2">SUBSEQUENT REPORT OF:</td> </tr> <tr> <td>PERFORM REMEDIAL WORK ☐</td> <td>PLUG AND ABANDON ☐</td> <td>REMEDIAL WORK ☐</td> <td>ALTERING CASING ☐</td> </tr> <tr> <td>TEMPORARILY ABANDON ☐</td> <td>CHANGE PLANS ☐</td> <td>COMMENCE DRILLING OPNS. ☐</td> <td>PLUG AND ABANDONMENT ☒</td> </tr> <tr> <td>PULL OR ALTER CASING ☐</td> <td>OTHER ☐</td> <td>CASING TEST AND CEMENT JOB ☐</td> <td></td> </tr> </table>			NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:		PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐	TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒	PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:																
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐															
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒															
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐																

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

T.D. 11,801', PBTD 10,000. This well was plugged and abandoned in the following manner:

1. MIRU pulling unit. Pulled tbg. dumped 4 sx cement on Model DB pkr. @ 9650'. Set CIBP on wire line prematurely @ 7230'. Pushed CIBP to 7536.80'. Bill Gressett w/NMOCC in Artesia gave approval to use the CIBP set @ 7536.80' to plug off Wolfcamp. Ran 2nd CIBP and set @ 7535'. Dumped 4 sx cmt on top of CIBP 7535-7500.
2. RU csg. jacks. Established free pt. @ 6600'. Shot @ 6552'. POOH with 5-1/2" csg.
3. RIH w/2-7/8" tbg. OE'D. Spotted 100 sx cement plug 6600-6300'.
4. Spotted 35 sx cement plug 5200'-5000'. Witnessed by Leland Mermis w/NMOCC.
5. Spotted 50 sx cement plug 3150'-3050'.
6. Spotted 10 sx cement top plug in 9-5/8" csg.
7. Installed 4" dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED E. Spaulder TITLE Region Oper. Manager DATE 6/13/77

APPROVED BY Leland Mermis TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: