

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR  
J. C. Williamson & D. W. Underwood et al

3. ADDRESS OF OPERATOR  
P.O. Box 16, Midland, TX 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface  
1980' FS & EL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)  
3280.7 GR

RECEIVED

RECEIVED

5. LEASE DESIGNATION AND SERIAL NO.  
0556290

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Williamson Federal

9. WELL NO.  
34

10. FIELD AND POOL, OR WILDCAT  
East Burton Flat-Atoka

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 9, T20S, R29E

12. COUNTY OR PARISH  
Eddy

13. STATE  
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

ARTESIA, OFFICE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting; any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Set Bridge plug @ 10,990' Perf Atoka @ 10,927-29-31  
Frac @ 12,000 gals. + 20,500# sand + 30 tons  
Dr. Tbg @ 10,891. Pkr @ 10,827'. Clean  
Well & test.

Set Bridge plug @ 10,990'. Perforated Atoka @ 10,927 - 29 - 31. Frac @ 12,000 gals. + 20,500 pounds of sand & 30 tons of CO2 Tubing @ 10,891. Pkr @ 10,827'. Clean well & test.

monow zone abandoned 10-10-76-2

POSTED ID-2  
ZONE ABAND  
10-07-76

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Operator

DATE 10/18/76

(This space for Federal or State office use)

APPROVED BY

TITLE ACTING DISTRICT ENGINEER

DATE OCT 26 1976

CONDITIONS OF APPROVAL, IF ANY: