

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

SEP 20 1993

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-6322	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

6. Indicate Type of Well OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
8. Name of Operator General Atlantic Resources, Inc. ✓		8. Farm or Lease Name Burton Flat Deep Unit
9. Address of Operator 410 17th Street, Suite 1400, Denver, CO 80202		9. Well No. 13
10. Location of Well UNIT LETTER <u>0</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>28</u> TOWNSHIP <u>20 S</u> RANGE <u>28 E</u> NMPM.		10. Field and Pool, or Wildcat Burton Flat Morrow
11. Elevation (Show whether DF, RT, GR, etc.) 3219' GR, 3235' KB		12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Plug back Morrow, Perf Strawn</u> <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pull tubing and packer out of hole. Set CIBP above existing Morrow perforations and set 35' cement on CIBP with dump bailer. Perforate Strawn zone from 10,274-10,284 and from 10,578-10,586'. Run 2-7/8" production tubing and packer. Set packer at 10,200'. Stimulate Strawn as required with acid. Set production equipment and test well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>RD Murray</u>	TITLE <u>Senior Operations Engineer</u>	DATE <u>9/15/93</u>
ORIGINAL SIGNED BY MIKE WILLIAMS SUPERVISOR, DISTRICT 11		
APPROVED BY	TITLE	DATE <u>SEP 22 1993</u>
CONDITIONS OF APPROVAL, IF ANY:		