

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-015-21166
Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
State Oil & Gas Lease No. SW 935
Lease Name or Unit Agreement Name OCOTILLO HILLS COM #1
Well No. 1
Pool name or Wildcat AVALON WOLFCAMP

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER TEMPORARILY ABANDON	
Name of Operator MEWBOURNE OIL COMPANY	
Address of Operator P.O. BOX 5270, HOBBS, NEW MEXICO 88241	
Well Location Unit Letter <u>F</u> <u>1650</u> Feet From The <u>NORTH</u> Line and <u>1650</u> Feet From The <u>WEST</u> Line Section <u>21</u> Township <u>21S</u> Range <u>26E</u> NMPM <u>EDDY</u> County	
Elevation (Show whether DF, RKB, RT, GR, etc.)	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MEWBOURNE OIL COMPANY PROPOSES TO RECOMPLETE WELL TO THE STRAWN FORMATION AS FOLLOWS:

- 1) MIRU WELL SERVICE RIG. INSTALL BOP.
- 2) PU 4 5/8" BIT AND BHA AND TIH.
- 3) DRILL CIBP AT 8820'. TEST CSG INTEGRITY.
- 4) DRILL CIBP AT 8875'. TIH TO PBTD AT 10785'. CIRC. HOLE CLEAN.
- 5) SET CMT RETAINER AT 8850'.
- 6) SQUEEZE EXISTING WOLFCAMP PERFORATION (8904'-8980') WITH 300 SX CLASS "H" CMT W/FLA.
- 7) DRILL OUT SQUEEZE AND TEST.
- 8) PERFORATE STRAWN FORMATION FROM 9764'-9908'(SELECTED HOLES).
- 9) ACIDIZE PERFORATIONS. FLOW AND EVALUATE.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Monty Whetstone

TITLE MANAGER OF PRODUCTION

DATE 10-06-97

TYPE OR PRINT NAME MONTY WHETSTONE

TELEPHONE NO. 393-5905

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUN
DISTRICT II SUPERVISOR

APPROVED BY

TITLE

DATE

7-30-98

CONDITIONS OF APPROVAL, IF ANY: