Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED Budget Bureau No. 1004-0135

Expires: March 31, 1993

c15/6

5. Lease Designation and Serial No.

NMNM 8941- 5W982

Do not use this form for proposals to dr	AND REPORTS ON WELLS III or to deepen or reentry to a different reservoir. R PERMIT—" for such proposals	6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation Concurrent Z Com
1. Type of Well Oil Gas Well Well Other		8. Well Name and No.
2. Name of Operator OXY USA Inc.	16696	9. API Well No.
3. Address and Telephone No. P.O. Box 50250 Midland, TX	K 79710-0250 915-685-5717	30- <i>015-21242</i> 10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey D	escription) 28 VESW (K) Sec 23 T205 R23E	Burton Flat Wolframs, N. 11. County or Parish, State: 073520 Eddy NM
	s) TO INDICATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent Subsequent Report	Abandonment Recompletion Plugging Back	Change of Plans New Construction Non-Routine Fracturing
Final Abandonment Notice	Casing Repair Altering Casing Other Set CIBRATTA Morrow Acidi 20 Wolfcump	Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
		21VEB ³⁰³
SEE	OTHER SIDE OIL CO	N. DIV.
14. I hereby certify that the foregoing is true and correct	D avid Stewart Title Regulatory Analyst	Date 3/25/96
(This space for Federal or State office use)	1100	
Approved by	Tide	Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements

ATTACHMENT 3160-5 OXY USA INC. GOVERNMENT Z #1 SEC 23 T20S R28E EDDY COUNTY, NM

TD - 11485' PBTD - 10015' PERFS - 9219-9303'

MIRU PU 1/15/96, PUMP 10# BW TO KILL WELL. ND WH, NU BOP, POOH W/ PKR & TBG. RIH W/ CIBP & SET @ 10950', RIH & DUMP 4sx (35') CMT ON TOP, POOH. RIH W/ CIBP & SET @ 10050', DUMP 4sx (35') CMT ON TOP, POOH. RIH W/ PERMA-LATCH PKR, ON/OFF TOOL & 2-7/8" TBG & SET PKR @ 9187', LOAD & TEST CSG TO 500#, OK, ND BOP, NU TREE. ACIDIZE WOLFCAMP PERFS 9219-9303' W/ 3000gal 15% NEFE HCL ACID FOAMED W/ 1000 SCF/BBL N2, MAXP-4600#, ISIP 2900#. FLOW WELL BACK 10hrs FOR 17-BO 332-BW @ AVG FTP-100#. SITP-950#, BLED WELL DOWN IN 2hrs FOR 2-BO, 3-BW, RIH & SWAB 2-BO, 89-BW IN 9hrs. ND TREE, NUBOP, REL PKR & POOH. RIH W/ TAC & 2-7/8" TBG & SET @ 9532', TAC @ 9121'. NDBOP, NUWH, RIH W/ 2-1/2"X 1-1/2"X 20' RHBC PUMP ON 66 RD STR. RDPU 1/30/96. SI WO PMP EQP. START WELL PUMPING 2/8/96 & TEST WELL AS FOLLOWS:

TEST	OIL	WATER	<u>GAS</u>
24HRS	34	69	116
16HRS	19	82	65
24HRS	20	21	45
24HRS	20	28	119
24HRS	6	100	84
24HRS	21	100	83
24HRS	17	44	6 6
24HRS	48	120	97
24HRS	2 2	78	144
24HRS	29	84	165
24HRS	34	116	126
24HRS	30	50	132
24HRS	36	61	141
24HRS	29	42	143
24HRS	30	60	139
24HRS	7	56	139
24HRS	43	28	134
24HRS	22	43	130
24HRS	25	45	126

NMOCD POTENTIAL TEST 2/28/96

43 16 136 37.2 API 3163-GOR 24HRS