

UNITED STATES N.M.O.C.D. COPY
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
(Other instruction
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

N M 0490017-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Fasken Federal

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Avalon

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

5-21-26

12. COUNTY OR PARISH

Eddy

13. STATE

N M

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Ralph Nix

3. ADDRESS OF OPERATOR

P. O. Box 617 Artesia, N M 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FWL & 660' FSL Sec. 5 Twn. 21 S., R. 26 E.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3213

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Up date on Rework

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Ran Guiverson Uni 6 packer to 10,521' and swabbed well down with slight show of gas (too small to measure) from perforations 10,572 - 620' and 734-750'.

Moved packer to 10,674' and tested perforations 10,734-750'. Swabbed down with no show of gas or fluid. Treated zone with 1,500 gallons acid and swabbed down immediately with no show of gas or water. Tested 24 hrs. no fluid or gas.

Perforated 10788-93 10 holes ran packer to 10,674 and set. Swabbed good show of gas and considerable water.

Plan to pull packer and tubing, run a cast iron bridge plug to 10,300' and perforate Atoka zone 10,016-22' and test. Waiting on pulling unit.

RECEIVED

DEC 13 1979

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Dalton Kitchel

TITLE Agent

DATE Dec. 12, 1979

(This space for Federal or State office use)

APPROVED BY (Ord. Sgd.) ALBERT R. STALL

TITLE ACTING DISTRICT ENGINEER

DATE DEC 13 1979

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side