

2000# at end of test. Control valves operated as indicated on closing unit manifold at end of test. Bop extentions were not hooked up - rig nipping up. No test desired to top of casing using packer, nor to the upper kelly cock, to the lower kelly cock, to the drill pipe safety valve, to the check valve off stack on kill line, or to the valves and fittings off the choke-manifold cross.

YELLOW JACKET TOOLS AND SERVICES, INC.

ODESSA, TEXAS

Test made by Roscoe Maxwell *Roscoe Maxwell*