NO. OF COPIES RECEIVED	1								Form C-1	13	
DISTRIBUTION	┼┷┯								Supersed	es Old	
SANTA FE	╉╾╌┾		NFW		UL CONS			NF D	C-102 and Effective		
FILE	 	4		menice e		ERVATENC	E.L.A				
U.S.G.S.	† · †								5a. Indicate '	Type of Le	ase
LAND OFFICE						1111	25 19	75	State X		Fee
OPERATOR	1		JUL 2 5 1975						5. State Oil & Gas Lease No.		
	<u> x _ </u>					_			0G-60)27	
(DO NOT USE THIS FO USE	SUN MAPPL	IDRY	NOTICES A	ND REPO	RTS ON	WELLS	SIA, OF	FICE			
									7, Unit Agree	ement Name	2
OIL GAS WELL WELL	LX		OTHER-								
2. Name of Operator									8. Farm or L	ease Name	
Harvey E. Yates Co., Inc.								Cedar Hills Com.			
3. Address of Operator									9. Well No.		
Suite 1000, Security Natl. Bank Bldg., Roswell, N.M. 88201								2			
4. Location of Well UNIT LETTER G, 1650 FEET FROM THE NOTTH LINE AND 1980 FEET FROM								Und. Burton Flat Strawn-Morrow			
UNIT CETTER	, _			-ROM THE				FEET FROM		IIIII	IIIIIII
THE <u>East</u> L	.INE, SI	ECTION	15	TOWNSHIP .	21S	RANGE	27	<u>Е</u> кмрм.			
	\overline{III}	\overline{III}	15. El	evation (Sho	w whether	DF, RT, GR, et	c.)		12. County		MMM
		///.		331	0 GR	•			Eddy		
16.	Cheo	k A	ppropriate B	Sox To Inc	dicate N	ature of Nor	ice Re	port or Oth	er Data		
NOTIC			TENTION TO		1			•	REPORT	DF:	
PERFORM REMEDIAL WORK]•		F	PLUG AND ABAI		REMEDIAL WOR	ĸ		AL	TERING CAS	
TEMPORARILY ABANDON	Ī					COMMENCE DRI	LLING OPNS		PL	UG AND ABA	NDONMENT
PULL OR ALTER CASING											
	_					OTHER	Comp	<u>letion V</u>	Vork		X
OTHER											
			· · · · ·								

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1903.

- 1. Perforated 5¹/₂" casing in Morrow Section from 11,613-11,633 with 21 shots. Treated perfs with 2,000 gals. of $7\frac{1}{2}\%$ MS acid plus 1,000 SCF of nitrogen per bbl. Tested after swabbing at rate of 2650 MCFD. Set retrievable bridge plug.
- 2. Perforated 5¹/₂" casing in Morrow Section from 11,545-11,555 with 10 shots. Tested at rate of 3600 MCFD. React bridge plug.
- Perforated 5¹/₂" casing in Morrow Section from 11,422-11,448 3. with 13 shots. Spotted 250 gals. acetic acid. Did not test seperately. Reset bridge plug.
- Perforated 5¹/₂" casing 11,332-11,352 in Morrow Section with 4. 20 shots. Acidized with 5,000 gals. 7½%. Tested after swabbing 1,000 MCFD.

These are the 4 zones perforated and tested seperately in the Morrow Section.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Pare subite	TITLE <u> </u>	ngineer	DATE7/24/75
APPROVED BY W. a. Greaset	TITLE SUP	ERVISOR, DISTRICT II	DATE JUL 28 1975

CONDITIONS OF APPROVAL, IF ANY: