

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P. O. Box 1980 Hobbs, NM 88240

P. O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM 87410

Well APINO.	30-015-21492
5. Indicate Type or Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	OG-6027
7. Lease Name or Unit Agreement Name	CEDAR HILLS COM.
8. Well No.	# 2
9. Pool name or Wildcat	EAST CARLSBAD WOLFCAMP (GAS)

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well OIL <input type="checkbox"/> WELL GAS <input checked="" type="checkbox"/> WELL OTHER	2. Name of Operator Harvey E. Yates Company	3. Address of Operator P.O. Box 1993, Roswell, NM 88202 1-505-623-6601
4. Well Location Unit Letter <u>G</u> : <u>1,650</u> Feet From The <u>NORTH</u> Line and <u>1,980</u> Feet From The <u>EAST</u> Line	Section <u>15</u> Township <u>21S</u> Range <u>27E</u> NMPM County	10. Elevation (Show whether DF, RKD, RT, GR, etc.) 3300' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103

1. SET CIBP @ 9475' +/- PLUS 35' CMT ON TOP. 25 3x5
2. SPOT 100' CMT PLUG @ 8898' +/- (TOP OF WOLFCAMP).
3. FREE POINT 5 1/2" CSG & ATTEMPT TO RECOVER 7600' 5 1/2" CASING. —
4. SPOT 100' PLUG (50' IN & OUT OF CUT OFF). TAG THIS PLUG.
5. SPOT 100' PLUG @ 5265' (TOP OF BONE SPRING) 25 3x5
6. SPOT 100' PLUG @ 2993' (50' BELOW INTERM. SHOE & 50' INSIDE CSG.) TAG THIS PLUG.
7. SPOT 100' PLUG @ 667' (ACROSS SURFACE SHOE @ 617'). TAG
8. SPOT 10 SK SURFACE PLUG.
9. CUT OFF WELL HEAD & WELD ON DRY HOLE MARKER.
10. BACKFILL ALL PITS & CLEAN LOCATION.

NOTIFY OCD II (ARTESIA) @ 1-505-748-1283 24 HOURS PRIOR TO STARTING.

RECEIVED

OCT 23 1995

OIL CON. DIV.
DIST. 2

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ray F. Nokes TITLE PROD. MGR. / ENGINEER Date 10/9/95
TYPE OR PRINT NAME RAY F. NOKES TELEPHONE NO. 1-505-623-6601

(This space for State use) ORIGINAL SIGNED BY TIM W. CUM

Approved by _____ Title _____ Date OCT 25 1995
Conditions of approval, if any:

