

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I  
P. O. Box 1980 Hobbs, NM 88240

P. O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT II  
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd, Aztec, NM 87410

Well APINO.	30-015-21492
5. Indicate Type or Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	OG-6027
7. Lease Name or Unit Agreement Name	CEDAR HILLS COM.
8. Well No.	# 2
9. Pool name or Wildcat	EAST CARLSBAD WOLFCAMP (GAS)

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well OIL <input type="checkbox"/> WELL GAS <input checked="" type="checkbox"/> WELL OTHER	2. Name of Operator Harvey E. Yates Company	3. Address of Operator P.O. Box 1993, Roswell, NM 88202 1-505-623-6601	4. Well Location Unit Letter <u>G</u> : <u>1,650</u> Feet From The <u>NORTH</u> Line and <u>1,980</u> Feet From The <u>EAST</u> Line Section <u>15</u> Township <u>21S</u> Range <u>27E</u> NMPM <u>EDDY</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3300' GL			

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103

- 2-28-96 SET CIBP @ 9475'. 2-29-96 SPOT 10 SK PLUG (35' ON TOP OF CIBP)
- 2-29-96 SPOT 30 SK PLUG (100' CMT) @ 8700'
- 3-1-96 CUT 5 1/2" CSG @ 7260'.
- 3-5-96 SPOT 45 SK PLUG (100' PLUG (50' IN & OUT OF CUT OFF)). TAG PLUG @ 7200'.
- 3-5-96 SPOT 45 SK PLUG (100' PLUG @ 5260' (TOP OF BONE SPRING)).
- 3-5-96 SPOT 45 SK PLUG (100' PLUG) @ 2993'. TAG PLUG @ 2875'.
- 3-6-96 SPOT 45 SK PLUG (100' PLUG) @ 667'. TAG @ 550'.
- 3-6-96 SPOT 10 SK SURFACE PLUG.
- 3-6-96 CUT OFF WELL HEAD & WELD ON DRY HOLE MARKER.
- BACKFILL ALL PITS & CLEAN LOCATION.

GARY WILLIAMS w/ OCD II ON LOCTION OFF & ON DURING P&A OPERATIONS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE	<u>Ray F. Nokes</u>	TITLE	<u>PROD. MGR. / ENGINEER.</u>	Date	<u>3/12/96</u>
TYPE OR PRINT NAME	<u>RAY F. NOKES</u>	TELEPHONE NO.	<u>1-505-623-6601</u>		

(This space for State use)

Approved by	<u>[Signature]</u>	Title	<u>Ed Roy</u>	Date	<u>13/4/96</u>
-------------	--------------------	-------	---------------	------	----------------

Conditions of approval, if any:

RECEIVED

MAR 16 1996

OIL CON. DIV.

DIST. 2

Post FD-2

3-22-96

P & A