

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS
RECEIVED

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other

MAY 05 1983

2. NAME OF OPERATOR

CITIES SERVICE OIL & GAS CORPORATION
ARTESIA OFFICE

3. ADDRESS OF OPERATOR

P. O. BOX 1919 - Midland, Texas 79702

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 660' FNL & 1980' FWL
AT TOP PROD. INTERVAL: Same as above
AT TOTAL DEPTH: Same as above

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☒
(other) ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

OTD 11,730' Lime & Shale, OPBTD 10,900'. It is proposed to plug and abandon this well in the following manner:

1. MIRU pulling unit. Load hole w/BW. NDWH & NU BOP. RU WL. Set blanking plug @ 8909'. CHC. Spot a 150' cmt. plug from approximately 8900-8750' across the top of the Wolfcamp. POOH.
2. RU and run free point. Cut csg. @ approximately 7750'. POOH.
3. RIH w/OE'd tbg. to 7800'. CHC. Spot a 100' cmt. plug from approximately 7800-7700' 1/2 in and 1/2 out of 5-1/2" csg. stub.

SEE REVERSE SIDE
Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Elmer Stutz TITLE REG. OPEP. MGR. -- DATE 4-20-83

APPROVED (This space for Federal or State office use)

APPROVED BY (Sig. Sec.) PETER W. CHESTER

CONDITIONS OF APPROVAL, IF ANY:

MAY 3 1983

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

GPO : 1981 O - 347-166

4. POOH to 7150' and spot a 100' cmt. plug from approximately 7150-7050' across the top of the 2nd Bone Springs Sand.
5. POOH to 5150' and spot a 100' cmt. plug from approximately 5150-5050' across the top of the Bone Springs.
6. POOH to 3052' and spot a 100' cmt. plug from approximately 3052-2942' $\frac{1}{2}$ in and $\frac{1}{2}$ out of 9-5/8" csg. shoe. *log on that this plug*
7. POOH to 450' and spot a 100' cmt. plug from approximately 450-350' $\frac{1}{2}$ in and $\frac{1}{2}$ out of 13-3/8" csg. shoe. POOH.
8. ND ROP & CO WH. Spot a 15 sack surface plug from approximately ~~50~~ 50'-0. Install dry hole marker to designate a plugged and abandoned location.