

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐
well well well

2. NAME OF OPERATOR
COQUINA OIL CORPORATION

3. ADDRESS OF OPERATOR
P. O. DRAWER 2960, MIDLAND, TEXAS 79702

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660' FWL & 1980' FSL Sec. 29
AT TOP PROD. INTERVAL: Same
AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☒
(other) ☐

SUBSEQUENT REPORT OF:

RECEIVED BY
MAR 23 1987
O. C. D.
ARTESIA OFFICE
RECEIVED
MAR 17 1987
SUNBELT LAND MANAGEMENT
CARRIZO, N.M.

5. LEASE

Wagner Federal NM-0400 512-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

9. WELL NO.

2

10. FIELD OR WILDCAT NAME

Avalon-Bone Springs

11. S. C., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 29, T20S, R27E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3210' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. RIH with CIBP & set @ approximately 6050' with 35' cement on top.
2. Fill hole with fluid.
3. Run free point on casing (5-1/2") & cut. (Depth unknown). Pull & LD 5-1/2" casing.
4. Set 100' plug at cut-off point on 5-1/2"; 50' in & 50' out and tag.
5. Set 100' plug at 8-5/8" shoe (1959'); 50' in & 50' out and tag.
6. Set 100' plug at 13-3/8" shoe (501') in 8-5/8"; 50' above and 50' below.
7. Set 15' plug at surface in 8-5/8".
8. Erect P&A marker above ground.
9. Restore location to original contours.

Note: See wellbore diagram attached.

Subsurface Safety Valve: Manu. and Type NA Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED D. Patrick Darden TITLE Engineer DATE March 16, 1987

(This space for Federal or State office use)

APPROVED BY Acting Area Manager TITLE DATE 3-26-87

CONDITIONS OF APPROVAL, IF ANY:

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.


Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

OPERATOR : COQUINA OIL CORP

LEASE : WAGNER FEDERAL WELL No: 2

LOCATION : S29-T20S-R27E



ZPR 10-29-86