

Directions to Little Box Canyon Unit No. 1:

Location: 1650' FSL, 1980' FEL, Sec. 7-21S-22E, Eddy Co., New Mexico

Directions:

Start at Carlsbad

Take Hwy. 285 toward Artesia 10 miles and turn left at Conoco Station on top of hill.

Go 9.2 miles to Y and take right fork.

Go 4.4 miles to Marathon Plant on south side of road.

Go past Marathon plant 5.7 miles and take the right fork onto a caliche road (there is a Great Western and El Paso sign at this point).

Continue westerly 6.7 miles passing the following landmarks:

2 miles road turning north to Great Western dry hole (and entrance road to CSO Co. Loafer Draw Unit A No. 1).

0.5 mile further to water tank on north side of road (take the trail bearing to the right).

0.6 mile further to gate (proceed through gate).

2.3 miles to Burro Hill

1.3 miles to trail turning to north
6.7 miles

Turn northerly on trail 3.7 miles to location passing the following landmarks:

1.0 mile to draw

0.1 mile to gate

0.1 mile to 2nd gate

2.5 miles to location
3.7 miles