NO. O. COPIES RECEIVED			i - 1909 Digwradau (111
SANTA H	NEW MEXICO OIL CONSURVA	TION COMMISSION	 + -1.1 ≤ and C-103 1 (free tive 1-)-6°
FILE		_	
U.S.G.S		ECEIVED	The second second second
LAND FICE			te 🗶 Fee
OPE OR		0 1075	$1 + \frac{1}{2} = \frac{1}{2} + $
		DEC 8 1975	
DO NOT USE THIS FORM FOR PE USE "APPLICA	RY NOTICES AND REPORTS ON WELL ROPOSALS TO DRILL OR TO DEEPEN OF PLUG DACK TO TION FOR PERMIT - " FORM C-1011 FOR SUCH PROP	S A DIFFERENCE RESIDER.	Millin Aller
GAS WELL	OTHER. Dry Hole	ARTESIA, OFFICE	7. Unit Agreement II in
Cities Service Oil Company			State CS
3. A Dress of Operator Box 1919 - Midland, Te	exas 79701	· · · · · · · · · · · · · · · · · · ·	a, Settats. 1
4. Location of Well			10. Finite Fried, or Wild of
UNIT LETTER L	1980 FEET FROM THE South	660 EXTERNO	Undesignated
	10N1710WNSHIP21S		- VIIIIIIIIIIIIIIIIIIIIIIII
15. Elevation (Show whether DF, RT, GF, etc.) 3233' DF			Line County County Eddy
^{16.} Check	Appropriate Box To Indicate Nature	of Notico Part of (
	NTENTION TO:		NT REPORT OF: _{re}
PERFORM REMEDIAL WORK	PLUG AND ABANDON		LTERDAN CT
TEMPORARILY ABANDON		ENCE DRILLING OPHS.	tters i Administratione 🕅 🗙
PULL OR ALTER CASING	CHANGE PLANS	Additional well	completion data x
OTHER			
17. Describe Proposed or Completed C work) SEE RULE 1103.	perations (Clearly state all pertinent details, and	d give parament parameters.	estre du propose

T.D. 11557' Sand & Shale. Plugged and abandoned. Released packer set @ 10999' and pulled packer and tubing. Set a CIBP @ 11100' and dumped 7 sacks of cement on top of CIBP @ 11100-11050'. Loaded hole with mud laden fluid. Shot off 5-1/2" casing @ 9479' but could not pull. Shot off 5-1/2" casing @ 9464' and pulled 235 jts. of casing. Displaced a 40 sack cement plug @ 9504 - 9404' (1/2 in and 1/2 out of 5-1/2" casing cut point @ 9464'). Displaced a 80 sack cement plug across top of Wolfcamp @ 8825 - 8625'. Displaced a 40 sack cement plug across top of 2nd Bone Springs sand @ 7100 - 7000'. Displaced a 40 sack cement plug across top of 2nd Bone Springs sand @ 7100 - 7000'. Displaced a 40 sack cement plug across top of 1st Bone Springs sand @ 6350 - 6250'. Displaced a 40 sack cement plug across top of for of cement plug with rotary bit to 4490'. Set down on plug w/52,000# - Held 0.K. Ran DST No. 2: 4325 - 4490' (165') in the Delaware sand (See results on well completion report). Spotted a 40 sack cement plug across top of Delaware sand interval covered in DST #2 @ 1375 - 1275'. Spotted a 80 sack cement plug @ 3280 - 3080'. WOC 48 hrs. Dressed off top of cement plug with rotary bit to 3120'. Ran and set 2-7/8" OD tubing with a RTTS tool @ 2848', bottom of tail pipe @ 3072' to test Delaware open hole 2989 - 3120'. 14 hr SITP 37#. Swabed -0- bbl. of oil + 13.8 bbls formation water/7 hrs. Acidized Delaware thru open hole 2989 - 3120' w/1500 gals 7-1/2% modified mud acid w/additives. Max. press. 1700#, min. press. 750#, ISIP 700#, AIR 2.3 B/M. Swabed -0- bbls. oil + 31 bbls. formation water/6 hrs. Released RTTS tool @ 2848' and pulled tubing. Circulated hole with mud laden fluid and spotted a 40 sack cement plug @ 3025 - 2925'

18. I hereby certify that the information above is true and complete to the best sector decledge of the

signed	Region Operation Manager	December 5, 1975
APPROVED BY Schering	TITLE	

:

. -

(1/2 in and 1/2 out of 9-5/8" casing shoe @ 2989!). Set a 10 sack cement surface plug @ 58 - 0' and installed a 4" dry hole marker extending 4' above the ground to designate a plugged and abandoned location.