

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-015-21568

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
Kuklah Baby

8. Well No.
001

9. Pool name or Wildcat
Carlsbad Delaware, So.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Ray Westall Operating

3. Address of Operator
P. O. box 4, Loco Hills, NM 88255 (505) 677-2370

4. Well Location
Unit Letter G : 2310 Feet From The North Line and 1650 Feet From The East
Section 24 Township 22S Range 26E NMPM Eddy County Col

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3185 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDON LINE <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <u>Plug Back</u>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

08/29/97 POOH w/pump
09/03/97 POOH w/tbg & rods
09/04/97 Set CIBP @ 3000' dump 35' cmt on top Perf 2902-2922 1 shot/ft
20 holes .45 cal
09/05/97 Acidize w/1000 gal 7 1/2% delaflow
09/09/97 Frac w/20,000 gal Quality Foam & 50,000# 20/40 sd
10/01/97 POOH w/pmp & rods set CIBP @ 2882' dump 35' cmt on top
10/05/97 Perf 2540 - 2550 21 holes 2 shot/ft .45 cal.
10/07/97 Acidize w/1000 gal 7 1/2% delaflow
10/10/97 Frac w/20,000 gal 50 Quality Foam & 50,000# 20/40 sd
Set rods & tubing 2 7/8" tbg set @ 2457'
10/13/97 Placed on production

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Guanel Harper TITLE Production Analyst DATE 01/29/98

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY TIM W. BURN
DISTRICT II SUPERVISOR

APPROVED BY _____ TITLE _____ DATE 2-11-98

CONDITIONS OF APPROVAL, IF ANY: