

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

CLSF

SUNDRY NOTICES AND REPORTS ON WELLS, 60010

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO

NM 0489599

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

ARCO EI Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Undesignated Bone Springs

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Unit 1, Sec. 13-T21S-R26E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

1. OIL WELL ☐ GAS WELL ☒ OTHER Plugback & Recomplete

2. NAME OF OPERATOR

Yates Petroleum Corporation

3. ADDRESS OF OPERATOR

105 South 4th St., Artesia, NM 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)

At surface

2310' FSL & 660' FEL

RECEIVED

APR 17 1989

O. C. D.  
ARTESIA, OFFICE

14. PERMIT NO.

API #30-015-21591

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3220' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Plugback, recomplete

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

Propose to recomplete well as follows:

1. MIRU. Load tubing. POOH w/tubing, packer and RBP.
2. Set CIBP approximately 8950' w/35' cement cap. Run CBL, locate top of cement.
3. Perforate Bone Springs Lime at 7829-37' (5 holes); 7970-84' (5 holes); 8092-8130' (7 holes); 8196-8218' (5 holes), total 22 .41" holes.  
Propose to treat each zone with 15% NEFE acid.

APR 7 11 13 AM '89

RECEIVED

18. I hereby certify that the foregoing is true and correct

SIGNED

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE Production Supervisor

DATE 4-5-89

FOR:  
TITLE

DATE

4-13-89

\*See Instructions on Reverse Side