	DEPARTM. OF THE INT		5. LEASE DESIGNATION A NM 3607	ND SERIAL NO.	
SUNDI (Do not use this for	RY NOTICES AND REPORT rm for proposals to drill or to deepen or 1 use "APPLICATION FOR PERMIT—" for s	IS ON WELLS plug back to a different reservoir. such proposals.)	6. IF INDIAN, ALLOTTEE	OR TRIBE NAME	
1. OIL GAB V			7. UNIT AGREEMENT NAM	t B	
2. NAME OF OPERATOR	/	TO THE PARTY OF TH	8. FARM OR LEASE NAME	2	
Quinoco Petrole	eum, Inc.	0.4007	Inexco	Inexco 9. wall no.	
3. ADDRESS OF OPERATOR		JUL 20 1981	9. WELL NO.		
P.O. Box 37811.	1, Denver, CO 80237 ort location clearly and in accordance with	any State regulrements.	10. FIELD AND POOL, OR	WILDCAT	
See also space 17 below.) At surface		ARTESIA, OFFICE	Burton - 11. smc., r., a., w., da ai	at place	
1650' FSL & 660	O' FEL		12- T215-2	36 E	
14. PERMIT NO.	15. ELEVATIONS (Show wheth	her DF, RT, GR, etc.)	12. COUNTY OR PARISH	18. STATE	
	3194.7' GR, 321	0.7' KB	Eddy	NM	
16.	Check Appropriate Box To Indica		or Other Data		
NOT	TICE OF INTENTION TO:		BENQUENT REPORT OF:		
TEST WATER SHUT-OFF	MULTIPLE COMPLETE	WATER SHUT-OFF FRACTURE TREATMENT	REPAIRING WI		
FRACTURE TREAT SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT		
REPAIR WELL	CHANGE PLANS	(Other)			
(Other)			sults of multiple completion of completion Report and Log form		
	plug and abandon the Inex hole w/9.5 ppg mud @ 10,950' + 35' cmt cmt from 7,600' - 7,500'				
os 100' 100' 200'	cmt from 2,600' - 2,500' cmt from 575' - 475' cmt from 200' to surface	2	ural state.		
os 100' 100' 200'	cmt from 2,600' - 2,500' cmt from 575' - 475'	2	ural state.		
os 100' 100' 200' Set	cmt from 2,600' - 2,500' cmt from 575' - 475' cmt from 200' to surface	e orface location to nat	CARLSBAD RESOU AREA HEADQUARTI	RECEIVED	
Work should b	cmt from 2,600' - 2,500' cmt from 575' - 475' cmt from 200' to surface P&A marker and restore su egin the 1st week of Augu	e orface location to nat	CARLSBAD RESOU AREA HEADQUARTI	RECEIVED	