

N. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

RECEIVED

NEW MEXICO OIL CONSERVATION COMMISSION

SEP 18 1979

O. C. C.
ARTERIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K5090 & K6598
7. Unit Agreement Name
8. Farm or Lease Name JCW State Com
9. Well No. 1
10. Field and Pool, or Wildcat Winchester - Morrow
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Howard Boatright Co., Inc.
3. Address of Operator P.O. Box 7251 Odessa, Texas 79760
4. Location of Well UNIT LETTER <u>0</u> <u>1980</u> FEET FROM THE <u>East</u> LINE AND <u>660</u> FEET FROM THE <u>South</u> LINE, SECTION <u>2</u> TOWNSHIP <u>20S</u> RANGE <u>28E</u> N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.) 3271.5 GR.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Set retainer at 9800'. Run tubing string into retainer and squeezed with 50 sacks of cement at 2800' OSE. Unstring from retainer and dumped 5 sacks on top of retainer. Work performed on 8-13-79.
- Cut 4 1/2 casing at 7181' and pulled out hole with casing.
- Run tubing and spotted a 65 sacks at 7281' waited on cement and tagged plug at 7011'.
- Pulled tubing to 4761 and spotted a 35 sacks.
- Pulled tubing to 2751' and pumped a 50 sack plug waited on cement and tagged plug at 2625 feet.
- Pulled tubing to 450 ft. and spotted a 35 sack plug.
- Pulled out hole cut off well head. Placed 10 sack surface plug. Installed dry hole marker and rigged down. 8-17-79.

*Noted
4D-2
9-21-79
P+H*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]* TITLE President DATE September 7, 1979

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: