		A-1	• • • • • • • • • • • • • • • • • • • •		_Surf. temp*F
Spec. gravity		Chloric	des	p	pm Res@•F 50 PSI Gauge
INDICATE TYP	E AND SIZE	OF GAS MEA	SURING DEVICE USE	D. <u>4 A.C</u>	ou ist dauge
Date Time a.m p.m	3126	Surfac e Pressur e psi	Gas Rate MCF	Liquid Rote BPD	Remark s
0215					Opened tool with a weak blow
022 0			·		Increasing to fair blow
0225					Good blow
023 0	14"				Put on ¼" choke
0245	=				
030 0	11				
0315	11				Closed tool
05 15					Opened tool with a fair blow
052 0		12			Blow increasing
0522	11	3/4			Put on choke
0530	11	1/2			Fair blow
0545	11	1 ₄		,	11
0600					Weak blow
0615	11				n ·
0630					п
0645	11				н
0700					
0715	11				Closed tool
1115					By-passed tool
					·
		 	 		