

NO. COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S		
LAND	PRICE	
OPER	OR	

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

NOV 21 1975

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CLEAN UP A WELL OR TO A DIFFERENT WELL. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

D. C. C.  
ARTESIA, OFFICE

☐ L ☐ GAS WELL ☐ OTHER- Dry Hole

1. Name of Operator  
Cities Service Oil Company

2. Address of Operator  
Box 1919 - Midland, Texas 79701

3. Location of Well  
UNIT LETTER K, 1980 FEET FROM THE South LINE AND 1980  
West LINE, SECTION 33 TOWNSHIP 21S RANGE 27E

15. Elevation (Show whether DE, RT, GE, etc.)  
3119' GR

☒ X

Tracy D Com.

1

Undesignated Morrow

Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE PRODUCTION <input type="checkbox"/>	OTHER <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CLEANING <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, including work) SEE RULE 1103.

T.D. 11,575' Shale. This well was plugged and abandoned in the following manner:

1. Spotted a 40 sack cement plug across top of Morrow @ 10950 - 10850'.
2. Spotted a 40 sack cement plug across top of Atoka @ 10675 - 10575'.
3. Spotted a 40 sack cement plug across top of Strawn @ 10065 - 9965'.
4. Spotted a 40 sack cement plug across top of Canyon @ 9820 - 9720'.
5. Spotted a 40 sack cement plug across top of Wolfcamp @ 8755 - 8655'.
6. Spotted a 40 sack cement plug across top of 2nd Bone Springs @ 7100 - 7000'.
7. Spotted a 40 sack cement plug across top of 1st Bone Springs @ 6350 - 6250'.
8. Spotted a 40 sack cement plug across top of Bone Springs @ 5220 - 5120'.
9. Spotted a 40 sack cement plug @ 3050 - 2950' (1/2 in and 1/2 out of 9-5/8" casing shoe @ 3000').
10. Set a 10 sack cement surface plug @ 58 - 0' and installed a 4" dry hole marker extending 4' above the ground to designate a plugged and abandoned location.
11. Location will be levelled and cleared of all equipment and debris.

18. I hereby certify that the information above is true and complete to the best of my knowledge.

SIGNED E. P. Miller TITLE Region Operation Manager November 19, 1975

APPROVED BY John G. Morris TITLE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: