

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND	PRICE
OPER	OR

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

FEB 19 1976

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG A WELL TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

<input type="checkbox"/> OIL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER: Dry Hole		U.C.C. ARTESIA, OFFICE	
1. Name of Operator Cities Service Oil Company		2. Well Agreement Name L-731	
3. Address of Operator Box 1919 - Midland, Texas 79701		3. Well Lease No. State CR Com.	
4. Location of Well UNIT LETTER B 660 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 16 TOWNSHIP 21S RANGE 27E		10. Well is Pool, or Wildcat Undesignated	
15. Elevation (Show whether DE, RT, GE, etc.) 3248' GR		12. County Eddy	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPER. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including completion date, if any proposed work) SEE RULE 1103.

T.D. 11721' Shale PBTD 9635'. Waiting on casing puller. We propose to plug and abandon this well in the following manner:

1. MIRU casing puller, load hole with mud laden fluid and pull tubing.
2. Cut off 5-1/2" casing @ approx. 8300' and pull out of hole.
3. Displace a 60 sack cement plug @ approx. 8375 - 8225' (1/2 in and 1/2 out of 5-1/2" casing stub @ approx. 8300').
4. Displace a 60 sack cement plug across top of 2nd Bone Springs Sand @ approx. 7100 - 6950'.
5. Displace a 60 sack cement plug across top of 1st Bone Springs Sand @ approx. 6350 - 6200'.
6. Displace a 60 sack cement plug across top of Bone Springs @ approx. 5175 - 5025'.
7. Displace a 40 sack cement plug @ approx. 3050 - 2950' (1/2 in and 1/2 out of 9-5/8" casing shoe @ 3000').
8. Spot a 10 sack cement surface plug @ approx. 58 - 0' and install a 4" dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED E. Spiller TITLE Region Operation Manager February 18, 1976

APPROVED BY W. A. Gressett TITLE SUPERVISOR, DISTRICT II FEB 19 1976

CONDITIONS OF APPROVAL, IF ANY:
Notify N.M.O.C.C. in sufficient time to witness spotting plugs.