

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Dry Hole		RECEIVED	
2. NAME OF OPERATOR Cities Service Oil Company ✓		SEP 28 1976	
3. ADDRESS OF OPERATOR Box 1919 - Midland, Texas 79701		O.C.C.	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FNL & 860' FWL of Sec. 17-T21S-R22E, Eddy Co., New Mexico		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
14. PERMIT NO.		7. UNIT AGREEMENT NAME	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4503' GR		8. FARM OR LEASE NAME Loafer Draw B	
		9. WELL NO. 1	
		10. FIELD AND POOL, OR WILDCAT Wildcat - Morrow	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 17-T21S-R22E	
		12. COUNTY OR PARISH Eddy	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

T.D. 3591' Shale. This well was plugged and abandoned in the following manner:

1. Spotted a 50 sack cement plug across top of Morrow @ 8175 - 8025'.
2. Spotted a 50 sack cement plug across top of Strawn @ 7560 - 7410'.
3. Spotted a 50 sack cement plug across top of Wolfcamp @ 5150 - 5000'.
4. Spotted a 35 sack cement plug across top of Abo @ 3690 - 3590'.
5. Spotted a 35 sack cement plug across top of Tubb @ 3100 - 3000'.
6. Spotted a 35 sack cement plug @ 1850 - 1750' (1/2 in and 1/2 out of 8-5/8" casing seat @ 1800').
7. Spotted a 10 sack cement surface plug @ 50 - 0' and installed a 4" dry hole marker extending 4' above the ground to designate a plugged and abandoned location.

USGS was notified and witnessed the plugging of this well.

RECEIVED
FEB 2 1976
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Region Operation Manager

DATE January 28, 1976

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

POSTED
P+A
3-19-76
ID-2