

Form 3160-5  
 (June 1990)

RECEIVED

UNITED STATES  
 DEPARTMENT OF THE INTERIOR  
 BUREAU OF LAND MANAGEMENT

APR 4 11 39 AM 1995

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
 Use "APPLICATION FOR PERMIT—" for such proposals

FORM APPROVED  
 Budget Bureau No. 1004-0135  
 Expires: March 31, 1993

5. Lease Designation and Serial No.  
 LC-065431

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Josephine Rodke Federal #2

9. API Well No.

30-015-21729

10. Field and Pool, or Exploratory Area

Parallel (Delaware)

11. County or Parish, State

Eddy County, New Mexico

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well  
☐ Gas Well  
☐ Other

2. Name of Operator

BASS ENTERPRISES PRODUCTION CO.

3. Address and Telephone No.

P. O. BOX 2760 MIDLAND, TEXAS 79702-2760 (915) 683-2277

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FNL & 1980' FWL, Unit Letter C,  
 Section 27, T-20-S, R-31-E

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☒ Other

Abandonment

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including the date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Bass Enterprises Production Co. requests approval of setting a cast iron bridge plug at 4400' to enable testing for casing integrity prior to Temporary Abandon approval.

- Contact BLM-Carlsbad 48 hours in advance at (505) 887-6544.
- MI and RU PU, POH with rods and pump (hang rods in derrick, send pump to shop for repair and storage). ND wellhead, install BOP, release 5" Baker Model "B" TAC set at 4390' with 8000# tension. POH with 2-3/8" 4.7#/ft J-55 tubing, LD TAC and bottom hole pumping assembly.
- PU and RIH with cast iron bridge plug sized for 5" 14.86#/ft casing on 2-3/8" tubing and set at or above 4400' (top perf at 4410'). POH with tubing and setting tool.
- PU S.N. and RIH with 2-3/8" tubing to +4370'.
- ND BOP, NU wellhead. RU pump truck with chart, circulate well with packer fluid, shut tubing in. Run casing integrity and bradenhead tests, RD pump truck.
- PU no-go and RIH with rods, install pumping tee and polish rod. RDPU.

CERTIFIED #Z 112 327 749-

BGH:PGO

14. I hereby certify that the foregoing is true and correct

Signed Keith E. BUCY Title DIVISION PRODUCTION SUPT.

Date 3/29/95

(This space for Federal or State office use)

Approved by JOE G. LARA Title REGIONAL ENGINEER

Date 4/27/95

Conditions of approval, if any: Tests to be performed within 30 days.