| Submit 3 Copies<br>to Appropriate<br>District Office   | State of New M<br>Energy, Minerals and Natural R  |   | 0155   | Form C-1Q3<br>Revised 1-1-89  |
|--|---|---|--|---|
| DISTRICT I<br>P.O. Box 1980, Hobbe, NM 88240<br>DISTRICT II<br>P.O. Drawer DD, Artesia, NM 88210   | OIL CONSERVATION DIVISION<br>P.O. Box 2088<br>Santa Fe, New Mexico 87504-2088   |   | WELL API NO.<br>30-015-21758<br>5. Indicate Type of Lease  |   |
| DISTRICT III<br>1000 Rio Brazos Rd., Aztec, NM 87410   |   |   | STA<br>6. State Oil & Gas Lease No.<br>K-6527  | TEX FEE   |
| SUNDRY NOTICES AND REPORTS ON WELLS<br>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A<br>DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"<br>(FORM C-101) FOR SUCH PROPOSALS.)   |   |   | 7. Lease Name or Unit Agree  | ment Name   |
| 1. Type of Well:       Oh,<br>WF11. XX       QAS<br>WF11. XX       Z. Name of Operator   | OTHER   | AUG 25  | Eddy "FV" State  | Com   |
| Premier Oil & Gas, Inc.<br>3. Address of Operator  |   | C.  | <ol> <li>well No.</li> <li>1</li> <li>Pool name or Wildcat</li> </ol>  |   |
| P.O. Box 1246, Artesia,<br>4. Well Location  | NM 88210  | ARTESIN.  | Bone Springs Unde  | signated  |
| Unit Letter <u>H</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>990</u> Feet From The <u>East</u> Line   |   |   |  |   |
| Section 25   |   |   | MFM Eddy   | County  |
|  | 10. Elevation (Show whether   | DF, RKB, RT, GR, etc.)  |  |   |
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  |   |   |  |   |
|  | ENTION TO:  | SUB   |  | ſOF:  |
|  |   | REMEDIAL WORK   |  | [ ] ]   |
| TEMPORARILY ABANDON  |   |   |  | DABANDONMENT  |
| OTHER:   |   | CASING TEST AND CEI<br>OTHER: Recomple  |  | $[\overline{\mathbf{x}}]$   |
| 12. Describe Proposed or Completed Operati   | Cons (Clearly state all pertinent details an  |   | · · · · · · · · · · · · · · · · · · ·  |   |
| work) SEE RULE 1103.<br>Rigged up well service un<br>9660' w/35' cement on top<br>top of plug. Perforated<br>Ran RTTS packer on tubing<br>packer at 7500'. Establish<br>& tubing. Ran E-2 drill of<br>in rotainer. Broke circula<br>temperature survey after &<br>casing set at 3050'. Copy<br>After WOC 72 hours, perfor<br>Acidized perfs w/2500gals<br>123,000# Ottawa 10/30 sand<br>After all load recovered<br>20/64" choke w/250 psig pi | it. Installed BOP, pul<br>of plug. Ran CIBP on w<br>1 holes in $5\frac{1}{2}$ " casing a<br>. Set packer at 7850'.<br>ned good circulation th<br>cement retainer on wire<br>ation & cemented $5\frac{1}{2}$ " ca<br>B hrs; top of cement be<br>of temperature survey<br>cated $5\frac{1}{2}$ " casing in 1st<br>15% NE-FE acid. Sand f<br>d & 3600# resin coated<br>well tested to tanks: 1 | led tubing. Ran<br>vireline & set pl<br>t 7600' (top of<br>Tested CIBP to 3<br>grough casing per<br>line, set retain<br>sing w/1475 sx c<br>whind 5½" casing<br>enclosed.<br>Bone Springs fr<br>ractured section<br>sand. | CIBP on wireline<br>ug at 8730' w/35'<br>cement 7665') beh<br>000 psig. Tested (<br>fs at 7600'. Trip<br>er at 7500'. Ran<br>of Premium plus cen<br>is 1200' from sur<br>om 6325-6518' w/19<br>w/6600gals Hyborg | & set plug at<br>cement on<br>ind 5½" casing.<br>OK. Reset<br>out w/packer<br>tubing; set<br>ment. Ran<br>face; 9-5/8"<br>5 shots.<br>gel cross link, |
| I hereby certify that the information above is true a  |   |   |  |   |
| SIONATURE () Curl De c   |   | ENGINE  | DATE _   | 11/30/93  |
|  | White   |   |  | one no. 748-2093  |
| (This space for State Use)<br>ATTROVED BY  | af h  | P   | DATE   | 12-21-93  |