

DST #8 7,644-7,694 (Bone Springs)

Packers failed

DST #9 7,450-7,500 (Bone Springs)

IF 30 min, good blow

ISI 60 min

FF 60 min, Good blow decreasing to weak blow

FSI 120 min

Combined recovery from DST #9, DST #10, DST #11 - 1023' SGCM
No sample chamber

IHP 3886

IFP 151-106

ISIP 106

FFP 93-88

FSIP 88

FHP 3825

RECEIVED

FEB 18 1977

D. C. C.
ARTESIA, OFFICE

DST #10 7,354-7,406 (Bone Springs)

IF 30 min, good blow

ISI 60 min

FF 60 min, weak blow

FSI 120 min

Combined recovery from DST #9, DST #10, DST #11 - 1023' SGCM
No sample chamber

IHP 3842

IFP 541-524

ISIP 526

FFP 554-557

FSIP 560

FHP 3797

DST #11 6,800-50 (Bone Springs)

IF 30 min, Weak blow

ISI 60 min

FF 60 min, Very weak blow, GTS 30 min, TSTM

FSI 120 min

Combined recovery from DST #9, DST #10, DST #11 - 1023' SGCM
No sample chamber

IHP 3784

IFP 592-584

ISIP 584

FFP 584-582

FSIP 587

FHP 3472