

Submit 3 Copies
to Appropriate
District Office

DISTRICT I
P.O. Box 1940, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION
P.O. Box 2088

San Jose, New Mexico 87504-2088

Form C-103
Revised 1-1-89

WELL API NO.
30-015-21938

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
Mesa Fuerta

8. Well No.
1

9. Pool name or Wildcat
Happy Valley (Strawn)

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3238 GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
Kaiser-Francis Oil Company /

3. Address of Operator
P.O. Box 21468, Tulsa, OK 74121-1468

4. Well Location
Unit Letter J : 1833 Feet From The South Line and 1980 Feet From The East Line
Section 33 Township 21S Range 26E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3238 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☒
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Plugging operations began 8/9/01 and were completed 8/20/01.

- 8-10-01 Set 5-1/2" CIBP @ 9800', ran dump bailer and cap w/ 35' of cmt., TOC @ 9765'.
- 8-13-01 Circulate hole w/ 10# gel. Spot 35 sx "C" cmt. from 8459 to 8359'.
- 8-14-01 Perf 5-1/2" csg. @ 6800', set pkr. @ 6550', sqz w/ 40 sx "C" cmt. @ 2-1/2 BPM @ 800 PSI, displaced TOC down to 6700', WOC & tag TOC @ 6630'.
- 8-16-01 Shot off 5-1/2" csg. @ 6516'.
- 8-16-01 Spot 45 sx "C" cmt. in and out of csg. stub plug @ 6566', WOC & tag @ 6422'.
- 8-17-01 Spot 50 sx cmt. @ 4500', WOC & tag TOC @ 4321'.
- 8-17-01 Spot 65 sx cmt. @ 2700', WOC & tag @ 2524'.
- 8-18-01 Set 9-5/8" CIBP @ 2515'.
- 8-20-01 Spot 35 sx "C" cmt. from 2515' to 2415'.
- 8-20-01 Spot 35 sx "C" cmt. from 365' to 265'.
- 8-20-01 Spot 20 sx "C" cmt. from 30' to Surface.
- 8-22-01 Cut off wellhead 4' below GL and install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE For my TITLE Agent DATE 8/21/01

TYPE OR PRINT NAME Charlotte Van Valkenburg 918-491-4314 TELEPHONE NO.

(This space for State Use)

APPROVED BY [Signature] TITLE Field DATE JAN 15 2002