

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

FEB 16 1977

Form C-103
Supercedes Old
C-102 and C-103
Effective 1-1-65

O. C. C.

ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator Llano, Inc. ✓	5. State Oil & Gas Lease No.
3. Address of Operator P. O. Box 1320, Hobbs, New Mexico 88240	7. Unit Agreement Name
4. Location of Well UNIT LETTER G 2310 FEET FROM THE North LINE AND 1980 FEET FROM THE east LINE, SECTION 17 TOWNSHIP 20S RANGE 26E NMPM.	8. Farm or Lease Name South Willow Draw "A" Com.
	9. Well No. 1
	10. Field and Pool, or Wildcat Und., West Bubbling Springs, Morrow
15. Elevation (Show whether DF, RT, GR, etc.) 3259.8 GL	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and abandoned as follows:
1-28-77: Set 40 sx cmt. plug from TD to 10,240'
Set 40 sx cmt. plug from 9,550' to 9,650'
Set 40 sx cmt. plug from 8,600' to 8,700'
Set 40 sx cmt. plug from 7,350' to 7,450'
Set 40 sx cmt. plug from 7,200' to 7,300'
Set 40 sx cmt. plug from 4,500' to 4,600'
Set 40 sx cmt. plug from 1,850' to 1,950'
Set 15 sx cmt. plug from 0 to 35'
Placed heavy mud between plugs.
Installed 4' dry hole marker.

*Plugged and abandoned as follows:
1-28-77
2-10-77*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>OKlear</u>	TITLE <u>Manager of Petroleum and Natural Gas Engineering</u>	DATE <u>February 14, 1977</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>JUL 20 1977</u>

CONDITIONS OF APPROVAL, IF ANY: