

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other

2. NAME OF OPERATOR
TXO Production Corp. ✓

3. ADDRESS OF OPERATOR
900 Wilco Bldg. Midland, Tx 79701

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: Unit F 2310 FNL 1980 FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☒
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☒

SUBSEQUENT REPORT OF:

(other) Pull approx 9100' 4 1/2" csg

5. LEASE
NM 24945
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Federal E
9. WELL NO.
1
10. FIELD OR WILDCAT NAME
Happy Valley (Atoka)
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec 4, T22S R26E
12. COUNTY OR PARISH
Eddy
13. STATE
NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3232KB

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Kill well.

Unseat UNI 6 w/on-off tool 10175 (11 K compr). Circ hole w/10# BW. TOH, TIH & set 4 1/2" CIBP @ 10100. Dimp 35' cmt.

Weld on pull nipple. Free pt 4 1/2" csg. (TDC 9150)

Cut 4 1/2" csg. TOH & LD. TIH w/tbg open ended.

Spot 15 sx "C" from 9700-9450

Spot 50 sx 9200-9000' (Assuming cut @ 9100')-Tag

Spot 90 Sx 8300-8100 → 6300/6450'

Spot 45 sx 4700-4500

Spot 45 sx 3600-3500'

Spot 75 sx 2750-2625 (50' into 9 5/8" csg shoe)-Tag

Spot 35 sx 2200-2100

Spot 35 sx 550-450

Subsurface Safety Valve: Manu. and Type _____ Spot 10 sx surface. _____ N/A Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Shirley Ann TITLE Production Engineer DATE 2-13-86

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE 2-26-86
CONDITIONS OF APPROVAL, IF ANY:

*Notify BLM 24 hrs before starting @ 505-887-6544

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between, and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.