

Form 3160-5
(November 1983)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other Instruction
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

clsr

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.)

RECEIVED

5. LEASE DESIGNATION AND SERIAL NO.

NMO354232 - SRM1317

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

ELIZONDO A FEDERAL

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

CARLSBAD MORROW, S.

11. SEC. T., R., M. OR BLK AND
SURVEY OR AREA

SEC 34 T21S R27E

14. PERMIT NO.

300152203200S01

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3143

12. COUNTY OR PARISH

EDDY

13. STATE

NM

Check Appropriate Box To Indicate Nature of Notices, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐
☐

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

FRAC TURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

WATER SHUT-OFF

FRAC TURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

☐
☐
☐
☒

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐
☒

RE-COMPLETION

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and five pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD - 11830'

PBTD - 11720'

MORROW PERFS - 11406' - 11568'

SEE OTHER SIDE

18. Thereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE

PROD. ACCT.

DATE

6/2/92

(This space for Federal or State office use)

APPROVED BY

[Signature]

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

MIRU PU-12/27/91, NDWH, NUBOP, REL PKR POOH W/ PKR & TBG. RIH & SET CMT RET @ 9497', M&P 100SX CL H CMT + .6% HALAD 9 & SQUEEZE PERFS 9579'-9585' TO 3500#, POOH, WOC. RIH & TAG CMT @ 9552', DO CMT TO 9705' PRES TEST TO 1000#, HELD OK. TAG & DO CIBP @ 11300' & CO OUT TO 11720'. RIH W/ PKR-11266', PROF NIP-ON/OFF TOOL-11264' & 2 7/8"TBG-11273'. PERF MORROW W/ 2 JSPF 11421,26,28,36,37,38,40,44,46,47,500,01,02,03,06,08,10,55,57,58,60,62,63,64,66,11568' TOTAL 52 HOLES, SWAB 0-BBL FLUID, NO SHOW OF OIL & GAS. SITP-250#, ACIDIZE MORROW PERFS 11406-11568' W/ 6000 GAL 7 1/2% NEFE HCL ACID W/ 1000 SCF N2/BBL, MAXP-5570, ISIP-4150. OPEN WELL TO PIT & FLOWED FOR 2 HRS FOR 0-O, 23-BLW IN 2 HRS, NO SHOW OIL OR GAS. SITP-1000# SWAB 0-O, LOAD WATER W/ SLIGHT SHOW OF GAS. FRAC MORROW PERFS 11406-11568' W/ 16500 GAL 2% KCL (25% METHANOL) + 16500 GAL CO2, 30000# SUPER RESIN COATED 20/40 SAND, MAXP-8400, ISIP-4300. OPEN WELL TO PIT & FLOWED 0-O, 75BLW IN 7 HRS W/ NO SHOW GAS OR OIL. SWAB TEST WELL FOR 7 DAYS FOR 0-O, WATER, & SLIGHT SHOW OF GAS. RDP-1/14/92, SI IN FOR ENGR EVAL & PBU.

WELL SI 1/14/92 - 3/30/92. HOOK UP COMPRESSOR, PUT WELL ON LINE 3/30/92 & TESTED WELL AS FOLLOWS:

TEST	MCFD	FTP	LP	SP	FLUID	
14HR	200	150	324	10	0	
24	69	40	313	10	0	
24	29	380	360	OPEN	0	FLW
24	29	350	348	"	0	"
24	37	"	"	"	0	"
24	37	"	"	"	0	"
24	35	"	345	"	0	"
24	35	"	"	"	0	"
24	56	250	324	15	0	"
24	50	150	462	15	0	
24	43	100	460	17	0	
24	28	50	324	8	0	
24	27	325	307	25/64	0	FLW
24	38	325	313	25/64	0	