

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

PAGE # 2

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
9. Well No.	
10. Field and Pool, or Wildcat	
12. County	

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	
2. Name of Operator	
3. Address of Operator	
4. Location of Well	
UNIT LETTER _____ FEET FROM THE _____ LINE AND _____ FEET FROM THE _____ LINE, SECTION _____ TOWNSHIP _____ RANGE _____ NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

and casing nipple would not hole.

5-5-77 Replaced faulty 9-5/8" casing nipple, drilled balance of top plug to 97' Kelly Drive Bushing and fell through plug, this cement was not as soft as the day before but also was not hard cement. There was no pressure increase going out of the bottom of the cement plug. Tagged second cement plug at 1695' Kelly Drive Bushing, shut down.

5-6-77 After being closed in 15 hours had no pressure or blow. Report the results to the New Mexico Conservation Commission, Artesia, New Mexico. Given permission to go ahead with top plug of cement. Set 60 sack cement plug from zero to 172' Kelly Drive Bushing, plug was 50% Class C cement and 50% Cal Seal. New Mexico Conservation Commission representative witnessed plugging and told us to put steel plate on 9-5/8" casing and not needed on the 13-3/8" Welded steel plate on 9-5/8" casing and put up the required hole marker. Plugged and Abandoned.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. B. Leuenberger TITLE Dist. Prod. Supt. DATE 5-12-77

APPROVED BY John M. Munn TITLE OIL AND GAS INSPECTOR DATE NOV 30 1977

CONDITIONS OF APPROVAL, IF ANY: