

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-22080
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. NM- V-2835
7. Lease Name or Unit Agreement Name WR STATE COM
8. Well No. #1
9. Pool name or Wildcat Alacran Hills A Toka

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Harvey E. Yates Company	
3. Address of Operator P.O. Box 1933, Roswell, New Mexico 88201	
4. Well Location Unit Letter <u>X</u> : <u>660'</u> Feet From The <u>South</u> Line and <u>990'</u> Feet From The <u>East</u> Line Section <u>06</u> Township <u>21S</u> Range <u>27E</u> NMPM <u>Eddy</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3207' G 3222' KB</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. CIBP @ 9725 w/35' cmt
2. CIBP @ 8750 w/35' cmt
3. Cut and pull 7400' 5 1/2" csg - Tag
4. Spot 100' across stub. 25sxs @ 4810 Tag
5. Spot 100' plug 2550' - 2650'. 30sxs
6. Spot 100' plug 550 - 623' 25sxs
7. Spot 10 sxs surface plug. Install pay hole marker.
gel between plugs

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jim Krum

TITLE Engineer

DATE 1/27/94

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY RAY SMITH

APPROVED BY

TITLE OIL AND GAS INSPECTOR

DATE

CONDITIONS OF APPROVAL, IF ANY:

* As Noted Above