

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL ☒ WELL GAS ☐ WELL OTHER- Dry Hole

2. Name of Operator
Mountain States Petroleum Corp. ✓

3. Address of Operator
P O Box 1936 Roswell, N Mex 88201

4. Location of Well
UNIT LETTER K 1980 FEET FROM THE South LINE AND 1980 FEET FROM
THE West LINE, SECTION 19 TOWNSHIP 21 S RANGE 27 E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name
Rayroux

9. Well No.
1

10. Field and Pool, or Wildcat
Carlsbad Delaware

15. Elevation (Show whether DF, RT, GR, etc.)

12. County

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	
		OTHER ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

No Oil Produced on extensive pump testing. Propose to plug and abandon with 75 sx cement plug 2550' to TD (2731'), 35 sx cement plug 570-670" and 15 sx cement surface plug with 4" x 4' dry hole marker. No casing to be pulled (circulated). Will notify Commission of proposed plugging date and time.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED K.C. Lavenor by rev TITLE Geologist DATE 10/3/79

APPROVED BY W.A. Gussert SUPERVISOR, DISTRICT 7 DATE OCT 5 1979

CONDITIONS OF APPROVAL, IF ANY: tag bottom plug plugging