	<u></u>	-	CISF
	UNITED STATES DEPARTMENT OF THE INTERIO BUREAU OF LAND MANAGEMENT		FORM APPROVED OMB No. 1004-0135 Division ires November 30, 2000
Do not use ti abandoned w	RY NOTICES AND REPORTS ON his form for proposals to drill or t rell. Use Form 3160-3 (APD) for suc	to re-enter mesia, NM B	S210 7 28 3 10 ttee or Tribe Name
	RIPLICATE - Other instructions of		7. If Unit or CA/Agreement, Name and/or No.
1. Type of Well	/	The State	
🔲 Oil Well 🚺 Gas Well 🛛	Conther Contract of the contra	13 107	/Well Name and No. Federal HQ #1
2. Name of Operator Yates Petroleum (✔ Corporation		9. API Well No.
3a. Address	3b. Pho	one No. (include area code)	30-015-22120
105 S. 4th St	Artesia, NM8821050c., T., R., M., or Survey Description)	5-748-1471	10. Field and Pool, or Exploratory Area Wildcat Strawn
	FWL of Section 5-T21S-R22	(Unit N SESW)	11. County or Parish, State
990° FSL & 1960	FWL OF Section J=1215-K22	LE (UNITE N, DEON)	Eddy Co., NM
12. CHECK A	PPROPRIATE BOX(ES) TO INDIC	ATE NATURE OF NOTICE, F	
TYPE OF SUBMISSION	1	TYPE OF ACTION	Fre City
	X Acidize existing Deep	en Production (Sta	
X Notice of Intent		ure Treat 🔲 Reclamation	Well Integrity
Subsequent Report	Cabing Hopen	Construction L Recomplete and Abandon L Temporarily A	bandon
Final Abandonment Notice	Convert to Injection		
following completion of the in testing has been completed. F determined that the site is read	ivolved operations. If the operation results in Final Abandonment Notices shall be filed only	a multiple completion or recompletion y after all requirements, including rec	fired subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once lamation, have been completed, and the operator has
 TIH with tubin and reverse acid of at 7508'±. Acidize perfor Swab/flow test Unset packer a 	out with treated water. I rations 7538-7695' (Strawn t for cleanup. and RBP. Move RBP to 6440	allcatcher. Set RBP Latch onto RBP and mo n) as necessary for p 0'± and packer to 599	at 5900'±. Pickle tubing ve to 7725'± and set packer roduction. 0'±.
	rations 6020-6410' (Cisco)) as necessary for pr	oduction.
7. Swab/flow test 8. POOH with tubi	ing and tools. Place well	l into production.	
NOTE: If decision be made to BLM and	n is made to commingle Cis 1 OCD.	sco and Strawn perfor	ations, application will
14. I hereby certify that the forego		<u>I</u>	
Name (Printed/Typed)		Title Operations T	echnician
<u>Rusty Klein</u>			
Signature Kustur	Nur-	Date December 12,	
	THIS SPACE FOR FED	ERAL OR STATE OFFICE US	
Approved by (ORIG	3. SGD.) LES BABYAK	FITEN EUM EN	GINEER JAN 0 5 2001
Conditions of approval if any ar	re attached. Approval of this notice does not gal or equitable title to those rights in the su o conduct operations thereon.	warrant or t	· ·
		for any person knowingly and willful latter within its jurisdiction.	ly to make to any department or agency of the United