

N.M.O.C.D. COPY  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.  
5. LEASE DESIGNATION AND SERIAL NO.  
NM 8419

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		NOV 20 1979	
2. NAME OF OPERATOR PETROLEUM DEVELOPMENT CORPORATION		O. G. C. ARTESIA, OFFICE	
3. ADDRESS OF OPERATOR 9720 B Candelaria NE, Albuquerque, New Mexico 87112		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  1980' FSL, 1980' FWL, Section 26, T21S, R22E		10. FIELD AND POOL, OR WILDCAT Loafer Draw-Strawn Gas	
14. PERMIT NO. --		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4240 KB	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 26, T21S, R22E	
		12. COUNTY OR PARISH Eddy	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☒

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Pull 2-7/8" tubing from on-off tool @ 8947'.
2. Dump 10 sx. 10-20 mesh sand on packer @ 8948'.
3. Re-perforate Strawn -- 8400'-8418'.
4. RIH w/2-7/8" tubing and packer set at approx. 8380'.
5. Acidize w/1500 gal. 7.5% MS acid.
6. Swab well in.
7. Fracture treat, if needed.

Anticipated commencement date: December 1, 1979.

RECEIVED

NOV 19 1979

U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

President

DATE

11/16/79

(This space for Federal or State office use)

(Orig. Sgd.) GEORGE H. STEWART

ACTING DISTRICT ENGINEER

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: