

OF COPIES RECEIVED	3
DISTRIBUTION	
SAN. A FE	/
FILE	/ ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

RECEIVED  
NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

AUG 8 1977

O. C. C.  
ARTESIA, OFFICE

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
-----

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator Morris R. Antweil
3. Address of Operator Box 2010, Hobbs, New Mexico 88240
4. Location of Well UNIT LETTER H 1980 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 10 TOWNSHIP 22-S RANGE 26-E N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.) 3179 GR

7. Unit Agreement Name -----
8. Farm or Lease Name Mesa Arriba
9. Well No. 1
10. Field and Pool, or Wildcat Undesignated
12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled 8-3/4" hole to TD 11,500'. Plugged and abandoned as follows:

40 sx. cement plug	10,950' -	11,050'
40 sx. cement plug	10,200' -	10,300'
40 sx. cement plug	9,920' -	10,020'
40 sx. cement plug	8,525' -	8,625'
40 sx. cement plug	6,500' -	6,600'
40 sx. cement plug	4,930' -	5,030'
40 sx. cement plug	3,500' -	3,600'
40 sx. cement plug	2,180' -	2,280'
10 sx. Surface plug and marker.		

P. & A. 31 July 77.  
Csg. left in hole 13 7/8" - 300 - 300' air  
9 7/8" - 2228 - 2100' air.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. M. Wilkins TITLE Agent DATE 5 August, 1977

APPROVED BY Mike Stubbelfield TITLE OIL AND GAS INSPECTOR DATE APR - 3 1978

CONDITIONS OF APPROVAL, IF ANY: