

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

MAY 21 '90

WELL API NO.

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Moutray Com

8. Well No.
#1

9. Pool name or Wildcat

Eddy Endos Morrow

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

Pecos Valley, Inc.

3. Address of Operator

P. O. Box 1598, Carlsbad, NM 88240

4. Well Location

Unit Letter J : 1880 Feet From The S Line and 2180 Feet From The E Line

Section

6

Township

20

Range

26

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3865 ft

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set 5 1/2" CIBP @ 9470', w/ 14 sks. of cement on top.
2. Set 35 sks. of cement @ 5 1/2" stub, 50' in & 50' out @ 8070'. Tag plug @ 7966'.
3. Set 30 sks. of cement @ 7526'.
4. Set 30 sks. of cement @ 7054'.
5. Set 30 sks. of cement @ 5200'.
6. Set 30 sks. of cement @ 3720'.
7. Set 30 sks. of cement @ 2812'.
8. Set 40 sks. of cement @ 1672', 50' in & 50' out @ 8 5/8" shoe. Tag @ 1560'.
9. Set 40 sks. of cement @ 417'.
10. Set 10 sks. of cement @ surface & install P & A marker.

Post ID-2
6-1-90
P & A

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

P & A Supervisor

SIGNATURE

Raymond Maldonado

TITLE

Baber Well Servicing Co.

DATE

5-16-90

TYPE OR PRINT NAME

Raymond Maldonado

TELEPHONE NO.

(This space for State Use)

APPROVED BY

Johnny Robinson

TITLE

OIL AND GAS INSPECTOR

DATE

9-20-91

CONDITIONS OF APPROVAL, IF ANY:

OK