1	-	معارية المرار		I
Submit 3 Cc pies to Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources Department		asi	Form C·103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO.	010
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico	87504-2088	30-015-22 5. Indicate Type of Lease	
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	and the second sec	526272829303 A	6. State Oil & Gas Lense	rate Fee X
SUNDRY NOTICES AND REPORTS ON WELLS (201) (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OF PENG BACK TO AN DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) ARTESIA			7. Lease Name or Unit Agreement Name	
1. Type of Well: OIL OIL X WELL X 2. Name of Operator	01 HER (1, 1, 2, 2, 1, 1, 2, 2, 1, 1, 2, 2, 1, 1, 1, 2, 2, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,		Anadarko Pardue Farms ANQ Com	
YATES PETROLEUM CORPOR	ATION		8. Well No. 1	
 Address of Operator 105 South 4th St., Artesia, NM 88210 Well Location 			9. Pool name or Wildcat Indian Basin Upper Penn, Assoc.	
	O Feet From The North	Line and1980	Feet From The	West Line
Section 27			NMPM Edd	y County
	10. Elevation (Show whether 3680	DF, RKB, RT, GR, etc.) 0' GR		
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
		REMEDIAL WORK		
	CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT			
PULL OR ALTER CASING		CASING TEST AND CE		
OTHER:		OTHER: Re-entry - spud & kick-off plug		
12. Describe Proposed or Completed Operations (Clearly state all periment details, and give persiment dates, including estimated date of starting any proposed work) SEE RULE 1103. 2-11-12-2000 - Moving in and rigging up rotary tools.				
2-13-2000 - Picked up drill collars and TIH. Nippled up and tested BOP to 3000 psi. Drilled surface plug. Picked up 6-1/4" drill collars. NOTE: Spudded in at 2:30 AM 2-13-2000 (8-3/4" hole).				
2-14-2000 - WOC. Picked up drill collars. Circulated. Tested casing to 1000 psi, OK. Drilled out plug #2. Picked up drillpipe. Circulated. Drilled plug #3. Picked up drill pipe. Tagged 4th plug at 5367'. TOOH. TIH. Circulated. Set a kickoff plug from 4300-				
4900' with 300 sacks Class H with 9/10% CD-32. WOC. 2-15-2000 - TD 4475'. Drilling cement. TIH and tagged cement at 4300'. Laid down 26				
joints of drillpipe. TOOH. TIH with bit and drill collars. Laid down 14 joints drillpipe. Dressed off cement plug from 4300-4475'. 2-16-2000 - Time drilling at 4516' cement. Drilled cement from 4475-4504'. Circulated &				
TOOH. Picked up directional tools. TIH. Installed rotating head rubber and washed to bottom. Set tool face and began time drilling.				
I hereby certify that the information above is true	and complete to the best of my knowledge and	belief. CONTINU		Eab 24 2000
SKONATURE Pustin 1		u <u>Operations</u> le	echnician DAT	
TYPE OR PRINT NAME Rusty Klein			TEL	EPHONE NO. 505/748-1471
(This space for Sinte Use)	W. Gum	District:	Sepervisor DAT	3·3· <i>co</i>
APPROVED BY	m	LE	DAT	E