

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN THE
DATE
(Reverse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

LC 062573

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	AUG 13 1978	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	O. C. C.	BIG EDDY UNIT
3. ADDRESS OF OPERATOR	ARTESIA, OFFICE	BIG EDDY UNIT
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1930' FSL + 660' FWL OF SECTION (IMPERATOR L.)		9. WELL NO. 57
14. PERMIT NO.	15. ELEVATIONS (Show whole feet, ft., or, etc.) GL 3232.6' LB 3246.6'	10. FIELD AND POOL, OR WILDCAT WILDCAT Nelson
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SEC. 30, T21S, R29E
		12. COUNTY OR PARISH EDDY
		13. STATE NEW MEXICO

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	☐	WATER SHUT-OFF	☐
FRACURE TREAT	☐	FRACURE TREATMENT	☐
SHOOT OR ACIDIZE	☐	SHOOTING OR ACIDIZING	☐
REPAIR WELL	☐	(Other)	☐
(Other)	☐	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give surface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

PLEASE SEE ADDED SHEETS.

RECEIVED

JUL 28 1978

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct.

SIGNED

(This space for Federal or State official use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY

TITLE

ACTING DISTRICT ENGINEER

DATE

AUG 17 1978

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

PLUG AND ABANDON PROCEDURE
BIG EDDY UNIT NO. 57
July 24, 1978

1. RU P/A unit and install manual 9" CPHL.
2. POOH with 2-3/8" 4.7#/ft J-55 EOE tubing, 3/4" rod installation, Watson FS pkr and bottom hole pump. Lay down rods, SN, perforated nipple, pkr and bull plug.
3. RU Dialog Col. and PU 5-1/2" bridge plug. RIH to 2800' and set bridge plug. Dump bail cmt from 2800-2765'. POOH.
4. RU and run free point indicator. 5-1/2" casing should be free at 2270'± (TOC). POOH.
5. RIH with jet cutter to free point and cut. POOH with 5-1/2" casing and lay down.
6. RIH with tubing to plug back (2765') and circulate hole with 25#/bbl brine gel mud.
7. Pull tbq to 25' below casing cutoff (2345') and spot a cement plug back to 2195', using 64 sx Class "H" neat, 15.6 ppg, 1.18 ft³/sk.
8. Pull tubing to 400' and set a cement plug from 400-300' using 30 sx Class "H" neat, 15.6 ppg, 1.18 ft³/sk.
9. POOH and lay down tubing.
10. RD P/A unit and BOPE
11. ND wellhead equipment. Spot a 20' plug from 20'-surface before installing dry hole marker.
12. Install 4" OD P/A marker 4' above mean ground level (New Mexico USGS requirements).
13. Clean location for final inspection.

2000

1975-1976

1977-1978

1979-1980

1981-1982

1983-1984

1975 TOS

1976 TOS

1977 TOS

1978 TOS

1979-1980 TOS

1981-1982 TOS

1983-1984 TOS

1985 TOS

1986 TOS

1870

1870

1870

1870

1870

1870

1870

1870

1870

1870

1870

1870

1870

1870

1870

SUSPENDED OPERATIONS

CONTR	Verna	3203' RT	6600' RT
-------	-------	----------	----------

F.R. 7-18-77
(Bone Spring)
4-10-78 AMEND SECTION: Formerly reported as Sec 19
4-3-78 TD 4725'; WOC
4-11-78 TD 4725'; Swbg
Perf (Bone Spring Lame) 2979-81'
4-18-78 TD 4725'; WOC
Swbd 100% SW (2979-81')
Sqzd 2979-81' w/200 sx
4-24-78 TD 4725'; PBD 3920'; TOP
Perf (Bone Spring) 2890-2920'
5-2-78 TD 4725'; PBD 3920'; TOP
Ppd 72 BW in 24 hrs (2890-2920')
5-9-78 TD 4725'; PRD 3920'; TOP
5-16-78 TD 4725'; PBD 3920'; Ppg wtr
5-22-78 TD 4725'; PRD 3920'; TOP
Ppd 8 BO + 52 BW in 24 hrs (2890-2920')
5-30-78 TD 4725'; PBD 3920'; TOP
6-6-78 TD 4725'; PRD 3920'; TOP 11-1- 0 GM

Ppd 8 BU 1 32 11-1-10 NM

RY

EDDY
BASS, PERRY R.

Wildcat
57 Big Eddy Unit
Sec 30, T21S, R29E

NM
Page #2

5-30-78	TD 4725'; PBD 3920'; TOP
6-6-78	TD 4725'; PBD 3920'; TOP
6-20-78	TD 4725'; PBD 3920'; TOP
7-18-78	TD 4725'; PBD 3920'; Prep D&A
11-20-78	TD 4725'; Dry & Abandoned
	Est. LOG TOPS: Ramsey Sand 2870', Cherry Canyon 4340'
11-4-78	COMPLETION ISSUED
11-25-78	RE-ISSUE OF SUSPENDED COMPLETION

11-1-10 NM
IC 30-015-70238-77

COUNTY EDDY FIELD Wildcat STATE NM
 OPR BASS, PERRY R. API 30-015-22223
 NO 57 LEASE Big Eddy Unit MAP
Sec 30, T21S, R29E CO ORD
1980' FSL, 660' FWL of Sec 11-1-10 NM
10 mi E/Carlsbad SPD 3-15-78 CMP 7-27-78

3 5/8" at 425' w/300 sx
 5 1/2" at 3908' w/650 sx

WELL CLASS: INIT WF FIN WF ELEV L & S			
FORMATION	DATUM	FORMATION	DATUM
TD 4725' (BSPG)		PBD	

DRY & ABANDONED

CENTER Verna OPRSTLEV 3233' GL PD 6600' RT

F.R. 7-18-77
 (Bone Spring)
 4-10-78 AMEND SECTION: Formerly reported as Sec 19
 4-3-78 TD 4725'; WOC
 4-11-78 TD 4725'; Swbg
 Perf (Bone Spring Lime) 2979-81'
 4-18-78 TD 4725'; WOC
 Swbd 100% SW (2979-81')
 Sqzd 2979-81' w/200 sx
 4-24-78 TD 4725'; PBD 3920'; TOP
 Perf (Bone Spring) 2890-2931'
 Acid (2890-2931') 5000 gals
 5-2-78 TD 4725'; PBD 3920'; TOP
 Ppd 72 BW in 24 hrs (2890-2931')
 5-9-78 TD 4725'; PBD 3920'; TOP
 5-16-78 TD 4725'; PBD 3920'; Ppg wtr
 5-22-78 TD 4725'; PBD 3920'; TOP
 Ppd 8 BO + 52 BW in 24 hrs (2890-2931')
 11-1-10 NM

EDDY
BASS, PERRY R.

Wildcat
57 Big Eddy Unit
Sec 30, T21S, R29E

NM
Page #2

5-30-78 TD 4725'; PBD 3920'; TOP
6-6-78 TD 4725'; PBD 3920'; TOP
6-20-78 TD 4725'; PBD 3920'; TOP
7-18-78 TD 4725'; PBD 3920'; Prep D&A
11-20-78 TD 4725'; Dry & Abandoned
Est. LOG TOPS: Ramsey Sand 2870', Cherry
Canyon 4340'
11-4-78 COMPLETION ISSUED
11-25-78 RE-ISSUE OF SUSPENDED COMPLETION

11-1-10 NM
IC 30-015-70238-77
