

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED *C/SR*  
BLM - CRA  
February 08, 1996

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir  
Use "APPLICATION FOR PERMIT" for such proposals

**SUBMIT IN TRIPLICATE**

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	5. Lease Designation and Serial No. LC-062573
2. Name of Operator Bass Enterprises Production Company	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. P. O. Box 2760 Midland, Texas 79702-2760 (915) 683-2277	7. If Unit or CA, Agreement Designation
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980' FSL & 660' FWL, SECTION 30, T21S-R29E, Unit Letter L	8. Well Name and No. Hopeful Federal #1
	9. API Well No. 30-015-22223
	10. Field and Pool, or Exploratory Area Undesignated (Delaware)
	11. County or Parish, State Eddy County, New Mexico

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
<input checked="" type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Other	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Bass Enterprises Production Company respectfully requests approval to plug and abandon on the Hopeful Federal #1.

Procedure as follows:

- 1) Load hole with 9.5# mud laden fluid. Spot minimum 15 sxs on top of CIBP at 2880'. (2880-2730')
- 2) Cut and pull 5-1/2" casing from +/-2200'.
- 3) Spot 30 sxs 50' in and out of 5-1/2" casing stub. WOC and tag.
- 4) Spot 40 sxs from 498'-398'. WOC and tag.
- 5) Mix 10 sxs surface plug.
- 6) Weld on dry hole marker.
- 7) Clean location.

Plugging depths per Armando Lopez (BLM).

CERTIFIED #P-973-823-507 JDL:PGS 12-27-00

14. I hereby certify that the foregoing is true and correct

Signed Keith E. Bucy KEITH E. BUCY

Title DIVISION PROD. SUPT.

Date 12/27/00

(This space for Federal or State office use)

Approved by ORIG. SGD. GARY GOURLEY

Title PE

Date 1/4/01

Conditions of approval, if any: