

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No.

5. LEASE DESIGNATION AND S.

NM 254 RECEIVED

6. IF INDIAN, ALLOTTEE OR TRIBE

MAR 10 1980

7. UNIT AGREEMENT NAME

O. C. D.

8. FARM OR RANCH NAME

Shells Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

6-21-24

12. COUNTY OR PARISH

13. STATE

Eddy

N. M.

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

DEPCO, Inc.

3. ADDRESS OF OPERATOR

800 Central, Odessa, Texas 79761

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

Unit Letter R, 1980 FS & EL, Sec. 6, T21S, R24E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3778.8 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) Plug Back ☒(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

2-20-80 Set RTTS @ 8838. Swab dry.

2-21-80 Acidized w/1000 gal 15% DS-30 acid. Swab dry.

2-22-80 Isolated perfs 8772-80, acidized w/1000 gal. 15% DS-30 acid. Swabbed well off and flowed 3 hrs. Trace water, no oil.

2-25-80 Re-acidized 8772-80 w/5000 gal. 15% DS-30 acid & 1000 SCF nitrogen. Started swabbing.

2-27-80 Set retrievable BP @ 8719 & RTTS @ 8458'. Acidized 8528-32 w/1000 gal. DS-30 acid. Swabbed dry.

2-28-80 Set BP @ 9053 & RTTS @ 8895'. Perf 8972-76 w/28PF.

2-29-80 Acidized w/1000 gal. DS-30 acid. Swabbed dry. Tested approx. 330 MCFPD.

3-3-80 Re-acidized w/4000 gal. DS-30 & 1000 SCF nitrogen. Swabbed dry.

3-4-80 Pulled BP & RTTS out and set Baker Lock-set pkf. @ 8672'. Swabbed well off.

3-5-80 SIIP 2750#. Opened well up making approx. 380 MCFPD, trace of cond. & small amount of water.

3-6-80 Testing.

18. I hereby certify that the foregoing is true and correct

SIGNED

D. R. Mason

TITLE Chief Clerk

DATE 3-10-80

(This space for Federal or State office use)

APPROVED BY (Orig. Sgd.) GEORGE H. STEWART

TITLE

DATE

MAR 11 1980

CONDITIONS OF APPROVAL, IF ANY:

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated by any State, on all lands in such State, pursuant to any State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.