3609' KB

ALUNITA

	Budget	Bures	u N	o. <b>42</b> -F	1142
LEASE	DESIGN	ATION	AND	SERIAL	NO.

	r instructions	on
verse	side)	

DEPARTMENT	OF	IHE	114.1

INTERIOR GEOLOGICAL SURVEY

NM	25347	
INL	ZJ341	

SUNDRY NOTICES AND REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAM

(Do not use this form fo Use "A	r proposals to drill or to dedien or plug back to a diff APPLICATION FOR PERMITA, for such property VE	erent reservoir.
1.  OIL GAS X O	THER 4 0 40	7. UNIT AGREEMENT NAME
2. NAME OF GPERATOR	FEB 1 8 19	8. FARM OR LEASE NAME
Monsanto Oil C	ompany	Catclaw Federal
3. ADDRESS OF OPERATOR	O. C. D.	9. WELL NO.
1300 One Midla	nd National Center, Mid 🗚 🕏 🗛	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
4. LOCATION OF WELL (Report lo See also space 17 below.) At surface	cation clearly and in accordance with any State require	nents.• 10. FIELD AND POOL, OR WILDCAT  Revelation Field
1880' FNL & 19	80' FEL Sec 10, T-22-S, R-25-E	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	Sec. 10, T-22-S, R-25-E
14. PERMIT NO.	10. ELEVATIONS (Show whether Dr. RI, GR, ecc.)	12. COUNTY OF TARISH 16. STATE

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16.

Form 9-331 (May 1963)

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF.			
EST WATER SHUT-OFF	PULL OR ALTER CASING		WATER SHUT-OFF	REPAIRING WELL	
RACTURE TREAT	MULTIPLE COMPLETE ABANDON®	<u>x</u>	FRACTURE THEATMENT SHOOTING OR ACIDIZING	ALTERING CASING ABANDONMENT*	
EPAIR WELL	CHANGE PLANS		(Other)	- Wales on Wales	
Other)			(Note: Report results of mi Completion or Recompletion	Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) •

To Plug and Abondon well.

1. Set CIBP @ 10470' cap w/20' cmt. W/dump bailer or 75 spif three tubing.

2. Cut and pull 5½" Casing @ 8690'±.


3. Spot 35 sxs. plug over 5½" casing stub. (atleast 150, 75' in tout of stub)

4. Spot 35 sxs. plug 4350'-4250'.
5. Spot 50 sxs plug 2450'-2350'. Tag This plug.

Spot 50 sxs. plug 450'-350'.

Spot 20 sxs. plug at surface.

Work will start approximately April 1, 1983.



FEB 1 6 1983

DIL & FT MINERALS MOIT, FOR TOE ROSWELL, NEW COLUMN

SIGNED APPROVED TITLE Regional Engineer	er
(This space for Federal or State office use)  APPROVED BY  CONDITIONS OF APPROVALE BONG 7 1983	DATE
FOR  JAMES A. GILLHAM  DISTRICT SUPERVISORE Instructions on Reverse Side	