

OIL CONS. COMMISSION, UNITED STATES  
Drawer DD DEPT. OF THE INTERIOR  
Artesia, NM 88210 GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 25347

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Catclaw Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Revelation

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 10, T-22S, R-25E

12. COUNTY OR PARISH 13. STATE

Eddy

New Mexico

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepening back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER ☐ DEC 9 1982 NOV 29 1982

2. NAME OF OPERATOR

Monsanto Oil Company

O. C. D.

O. C. D.

3. ADDRESS OF OPERATOR

ARTESIA, OFFICE

ARTESIA, OFFICE

1300 Midland National Center, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*

See also space 17 below.)  
At surface

1880' FNL &amp; 1980' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

RKB 3609

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other)

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

11/29/82:

Set CIBP at 10,645 with 10' cement on top. Perforate additional Morrow at 10,517, 19, 43, 45, 47; 10,587 - 89; 10,614-20; with 2JSPF. Stimulate w/3000 gals 7 1/2% acid + N<sub>2</sub>. Swab back load - place well on production.

RECEIVED

DEC 9 1982

OIL & GAS  
MINERALS MGMT. SERVICE  
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Regional Production Manager

DATE November 21, 1982

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE DEC 1 1982

FOR

JAMES A. GILLHAM  
DISTRICT SUPERVISOR

\*See Instructions on Reverse Side