

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

APR 11 1978

O. B. C.
OFFICIAL OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SRM 1216

API 30-015-22398

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Perry R. Bass ✓		Big Eddy Unit
3. Address of Operator		9. Well No.
Box 2760, Midland, Texas 79702		60
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>J</u> 1980 FEET FROM THE <u>South</u> LINE AND 1980 FEET FROM		Undes. Bone Springs
THE <u>East</u> LINE, SECTION <u>20</u> TOWNSHIP <u>21S</u> RANGE <u>28E</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
3204.3' GL 3222.3' KB		Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Plug back</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Confirming telephone conversation between Rex Robertson (Bass) and Mr. W. A. Gressett on March 26, 1978 concerning plugging back to the Bone Springs formation.

TD 12,208' SLM. 12,220' loggers.

Spot 90 sks cement from 12,162' back to 11,920'.
Spot 105 sks cement from 11,370' back to 11,170'.
Spot 50 sks cement from 10,700' back to 10,600'.
Spot 50 sks cement from 9,600' back to 9,500'.
Spot 50 sks cement from 7,700' back to 7,600'.
Spot 100 sks cement from 7,000 back to 6,838'.

10.1 PPG ^{muo} between plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>H. J. Wurtz, Jr.</u>	TITLE <u>Senior Production Clerk</u>	DATE <u>April 7, 1978</u>
APPROVED BY <u>W. A. Gressett</u>	TITLE <u>SUPERVISOR, DISTRICT II</u>	DATE <u>APR 11 1978</u>
CONDITIONS OF APPROVAL, IF ANY:		