

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form O-4103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-85

RECEIVED

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	APR 21 1980	5a. Indicate Type of Lease State <input type="checkbox"/> Free <input checked="" type="checkbox"/>
2. Name of Operator Michael P. Grace II	O. C. D. ARTESIA, OFFICE	7. Unit Agreement Name
3. Address of Operator P. O. Box 1418, Carlsbad, New Mexico 88220		8. Farm or Lease Name Corinne #1
4. Location of Well UNIT LETTER E 1980 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 25 TOWNSHIP 21S RANGE 26E N.M.P.M.		9. Well No. 1
		10. Field and Pool, or Wildcat Undesignated Morrow
15. Elevation (Show whether DF, RT, GR, etc.) 3142 GR		12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TO PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

T.D. of well 403'

4/10/80 Ran tubing in hole and set @ 396'. Pumped in 175 sx Halliburton Class "H" cement with 2% Cal Chl mix. Let set 2 1/2 hrs. Ran 4 yds 1" gravel on top. Went back & tagged at 330'. Pumped in 1 sack cotton seed hulls and 75 sx Hall. Cl "H" w/2% cal chl. Pulled tubing to 150'. Added 4 yds 1" gravel and tagged at 273'. Put in 10 yds gravel and tagged at 150'. Shut down for night.

4/11/80 Pumped in 1 sx cotton seed hulls. Pumped 100 sx Hall. Cl "H" cement w/2% cal chl. Pulled tubing. Pulled 105' of 20" casing. Ran tubing in hole tagged T.D. 80'. Pulled 1 jt tubing and set at 60'. Pumped in 300 sx Hall Cl "H" w/2% cc. Pulled tubing. Ran 1 short jt. tubing pumped in 25sx cement circl. to surface. Job complete.

4/14/80 Pumped in ready mix cement and set dry hole marker.

Will clean location (level pit and remove anchors)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Michael P. Grace II TITLE Agent DATE 4/18/80

APPROVED BY Mike Stullfield TITLE OIL AND GAS INSPECTOR DATE JUN 4 1980

CONDITIONS OF APPROVAL, IF ANY:

Posted  
FD-  
4-25-80  
P+H