			28 Yr				
Form 9-331 (May 1963)	DEPAR	SUBMIT IN TRIPLI (Other instructions verse side)	E* re-	Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO. NM-953]-B 6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
S (Do not use		OTICES AND REPORTS opomals to drill or to deepen or plu LICATION FOR PERMIT-" for suc	ng back to a different reservoir.				
1.					7. UNIT AGREEMENT NAME		
OIL GAS		R P&A					
2. NAME OF OPERATOR					8. FARM OB LEASE NAME		
INEXCO OIL COMPANY					Majoros Federal		
3. ADDRESS OF OPERATOR					9. WELL NO.		
1100 Milam Bldg, Suite 1900, Houston, TX 77002					2		
 LOCATION OF WELL (Report location clearly and in accordance with any State requirements. V E D See also space 17 below.) At surface 					10. FIELD AND POOL, OR WILDCAT Mar IC. Maderic Liber. Morrow		
NE 1/4 SE 1/4 Sec 23-T21S-R22E JUN 3 0 1978 1980' FSL & 810' FEL					11. SEC., T., R., M., OR BLK. AND SURVEY OR ARBA 23-T21S-R22E		
14. PERMIT NO.		15. ELEVATIONS (Show whether	er DF, RT, GR, etc.). C. C.		12. COUNTY OR PAR		
		4203' GR	ARTESIA, OFFICE		Eddy	New Mexico	
16.	Check	Appropriate Box To Indicat		, or C)ther Data		
NOTICE OF INTENTION TO:			8	SUBSEQUENT REPORT OF:			
TEST WATER SP	IUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF		REPAIRIN		
FRACTURE TREA	т	MULTIPLE COMPLETE	FRACTURE TREATMENT		ALTERINO	-V-	
SHOOT OR ACIDI	2E	ABANDON*	SHOOTING OR ACIDIZIN	G	ABANDON	MENT* /	
REPAIR WELL	REPAIR WELL CHANGE FLANS			(Other)			
(Other)			Completion or B	Completion or Recompletion Report and Log form.) t details, and give pertinent dates, including estimated date of starting any ions and measured and true vertical depths for all markers and sones perti-			

17. DESCRIBE PROPOSED OR COMPLETED OFERATIONS (Clearly state an pertinent actually measured and true vertical depths for all markers and sones pertiproposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.)*

DP stuck while drilling at 1097', was able to pull up 70' then unable to move. Bit stuck at 1024' top of fish at 598'. Plugged with 100 sx class "H" cmt in each stage placed four stages, set twelve 50 sx cmt stages from 345' to 140'. Cut off casing at surface, set 20 sx class "C" O' to 37'. Welded plate on top & set dry hole marker. Skidded rig to 2080' FSL & 810' FEL to drill Majoros Federal #2-Y.



true and correct 18. I hereby certify that the foregoing TITLE Asst. Drilling Administrator 6/20/78 SIGNED ODD6M (This space for Federal or State offic 1194 TITLE ACTING DISTRICT ENGINEER ara DATE ____. 1UN -3 0 - 1978 APPROVED BY APPROVAL, IF ANY: CONDITIONS

*See Instructions on Reverse Side