

COMPANY Southland Royalty Company

Well Trigg-Federal #1

Date

July 8, 1978

Test #	Items Tested	Pressure Pt.	Pressure	Minutes Held	Results
	Blind rams w/inside valves on manifold & valve on kill line closed.	Gauge down.			
1	"	"	2,400	los	Loss, repressure, replace "O" ring
2	"	"	2,200#		Loss, repressure, operate rams
3	"	"	1,500#		Leak @ inside flange on inlet valve on manifold.
4	"	"	3,000#		Same
5	"	"	3,000#	5 min.	No visible leak. Closed outside valve on manifold. No visible leak
	Pipe rams, valves on choke & kill lines closed @ stack.	Downhole pipe			
6	"	"	600#		Loss, repressure, leak thru rams
7	"	"	400#		Leak thru rams
8	"	"	400#		Same
9	"	"	400#		Same. Wait orig. to change rams
	Pipe rams w/inside valves on kill line closed, inlet valves on choke line closed.	"			
10	"	"	3,000#	7 min.	No visible leak, closed inside valve on choke line @ stack. Surged check valve. Okayed by toolpusher.
	Hydril/inside valves on choke & kill lines closed				
11	"	"	600#		Leak thru hydril
12	"	"	600#		Same, operate hydril
13	"	"	600#		Same
14	"	"	600#		Same, operate hydril
15	"	"	200#		Same
16	"	"	1,500#		Same