

July 14, 1978

Southland Royalty
1100 Wall Towers West
Midland, TX 79701

RE: Hydrostatic pressure test on your Trigg-Fed. #1 , located in the Carlsbad, New Mexico area in the Midland, Texas district.

Gentlemen:

We made a hydrostatic pressure evaluation to the above referenced job on July 8, 1978.

At the conclusion of testing there were leaks to the hydril.

There was no test desired to the casing, kelly cock or safety valve.

A schematic of surface control equipment has been prepared with leaks and or malfunctions posted thereto for your consideration. Also, enclosed is a copy of the report taken from field notes during testing and pressure readings of the test.

Your comments or suggestions as to how we may better serve you will certainly be appreciated.

Sincerely yours,

Yellow Jacket Tools and Services, Inc.

Jay E. Stubbs

Jay E. Stubbs

cll/Enclosures