

NEW MEXICO OIL CONSERVATION COMMISSION
WELL LOCATION AND ACREAGE DEDICATION PLAT

Form O-100
Supersedes C-128
Effective 1-1-65

All distances must be from the outer boundaries of the Section.

Operator FLAG-REDFERN OIL CO.		Lease MCCELLAN-FEDERAL COM.		Well No. 1
Unit Letter I	Section 11	Township 22-S	Range 24-E	County EDDY
Actual Footage Location of Well: 960 feet from the EAST line and 2310 feet from the SOUTH line				
Ground Level Elev. 4016	Producing Formation Cisco	Pool McKittrick Hills	Dedicated Acreage: 320 Acres	

1. Outline the acreage dedicated to the subject well by colored pencil or hachure marks on a map.
2. If more than one lease is dedicated to the well, outline each and identify the ownership thereof (both working interest and royalty).
3. If more than one lease of different ownership is dedicated to the well, have the interests consolidated by communitization, unitization, force-pooling, etc?

RECEIVED
MAY 5 1978
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

☒ Yes ☐ No If answer is "yes," type of consolidation Communitization

If answer is "no," list the owners and tract descriptions which have actually been consolidated. (Use reverse side of this form if necessary.)

No allowable will be assigned to the well until all interests have been consolidated (by communitization, unitization, forced-pooling, or otherwise) or until a non-standard unit, eliminating such interests, has been approved by the Commission.

J. L. McCellan Holly Eng. Etal 2-1-79 8665 480 acres	Jeanne Shelby 1-1-81 12828 160 acres
SECTION 11, Twp. 22-S, Rng. 24-E	
FLAG-REDFERN OIL COMPANY U. S. A. N. M. 12828	
640 acres	1 960'
	2310'

CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief.

Steve Rossler
Name

Steve Rossler
Position

Petroleum Engineer
Company

Flag-Redfern Oil Company
Date

May 4, 1978

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my knowledge and belief.

Date Surveyed

MAY 2, 1978

Registered Professional Engineer
and/or Land Surveyor

Reginald M. Buckner
Certificate No.

754

