

N.M.O.C.D. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0207950

RECEIVED

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

APR 22 1981

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Shell Federal Comm.

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Cemetery Morrow Gas

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 5, T-21-S, R-24-E

12. COUNTY OR PARISH

Eddy

13. STATE
New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry

2. NAME OF OPERATOR

DAVID FASKEN

3. ADDRESS OF OPERATOR

608 First National Bank Building, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

660' FWL & 3300' FSL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3565.7' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL


ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Set 10 sx cement surface plug inside 8-5/8" casing from 37' to surface (bottom of cellar)
2. Cut off 13-3/8" Bradenhead.
3. Weld cap on top of 8-5/8" & 13-3/8" casing.
4. Install dry hole marker.
5. Fill cellar & clean-up location.



18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Robert H. Angevine, Agent

DATE 4-20-81

(This space for Federal or State Approval)

APPROVED FOR RECORD
PETER W. CHESTER

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APR 21 1981

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

See instructions on Reverse Side