

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
(Other instructions
reverse side)

CE
FE

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

015F

5. LEASE DESIGNATION AND SERIAL NO.

NM 53219

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

M.H. Federal Com.

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

McKITTICK HILLS
Und. Morrow

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Section 1, T-22-S, R-24-E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Nearburg Producing Company

3. ADDRESS OF OPERATOR

P.O. Box 31405, Dallas, Texas 75231

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

1650' FWL & 660' FSL of Section 1

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3854' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Activity

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

11-16-88: Set C.I.B.P. at 10,210'. Dumped 2 SX cement on B.P. with dump bailer.

11-17-88: Perforated 8370'-80', 2 shots/ft. (21 holes) and 8333'-39', 2 shots/ft. (13 holes).
Swabbing water & trace of gas.

11-18-88: Swabbing formation water & trace of gas.

11-19-88: Swabbing formation water & trace of gas.

11-20-88: Shut down.

11-21-88: Set C.I.B.P. @ 8305'. Set Packer @ 8107'. Tested, Packer holding.

11-22-88: Perforated 8219'-31' with 2 shots/ft. swabbed 20 bbls. water, no oil or gas.

11-23-88: thru Swabbing formation water, very slight gas show.

11-28-88:

ACCEPTED FOR RECORD

DEC 14 1988

EB

18. I hereby certify that the foregoing is true and correct

SIGNED

Eddie J. Belmuel

TITLE

Operations Coordinator

DATE

12-7-88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side